

INS. REC. BY: Steve REF: CS/EA11012213/EUF3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMJ 4955L
at Workshop m/s _____
of _____
Insured: SFM 8628Y
Policy No. DMPPHQ21-006822
Claims No. DM21HO01793
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

X	X	X	X
N/S	O/S		
X	X	X	X

Bal. or Market Value: _____
IDAG Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs. 12 days Res.: Yes or No
Lum Sum: _____ % J-Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMJ4955L Yr Rogn: 8/3/19
Type: A Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Fit cc 1317
Colour: Red AC: _____ Insured / Std / NI / NA
Sp. Reading: 35626 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GK31341334
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NH / S/Rim / STD A/Rim or
Tyre Size: F: 185/55 R15
R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 30/11/21 D.O.I. 2/12/21
Survey held at Wah Hong
Des. of Damages: Frt / Rear / O/S / NIS / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MP-65K</u>
	Confirmed P/P \$8720.60, 12 repair days 10680.3
	(RED \$1959.70; 18%)

Date/Time, File Pass to? ☐ : Prelim. Report
9/12 TYPIST ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 12
Resurvey No. of Trip: 2

Arcl Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (\$ _____)
☐ : Wash and _____

Survey Fee:	
Transportation:	
\$ + RS. \$	
Funkas	
Others	
Total	

Report Form: TP
Amount Sum / P.P.: \$8720.60

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

**TP INSURER:
UNKNOWN****EQ Insurance Company Ltd (HQ)**

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	WH0939
Policy No:		Date of Loss:	30/11/2021
Vehicle Reg. No.:	SMJ4955L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LYE LI TENG, CHERYL		

Make/Model:	HONDA FIT, 1.3 GF CVT (A)	Vehicle Reg. Date:	08/03/2019
Vehicle Colour:	RED		
Engine No:	L13B1449342	Chassis No:	GK31341334
Odometer:	35618 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)
-------------------	---------------------------------------

COST OF CLAIMS	Amount
Parts	5,168.90
Miscellaneous Items	495.00
Labour	3,520.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,183.90
+ GST 7.00% (\$\$)	642.87
Nett Amount (\$\$)	9,826.77

This claim is handled by: THONG ZHONGMING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 01 Dec 2021)
Parts: 143 **HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: Wah Hong Motors & Credit Pte Ltd/SMJ4955L/01/12/2021 16:24
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear windscreen moulding / <i>nec</i>	0.00	0.00	*80.00 F
2	1		*Boot lid / <i>DD</i>	0.00	0.00	*570.00 F
3	1		*Boot lid outer center garnish X	0.00	0.00	*130.00 F
4	1		*Boot lid inner trim board X	0.00	0.00	*60.00 F
5	1		*Boot lid Weatherstrip / <i>CR4</i>	0.00	0.00	*50.00 F
6	1		*Boot lid logo badge / <i>nec</i>	0.00	0.00	*20.00 F
7	1		*Boot lid emblem "fit" / <i>nec</i>	0.00	0.00	*20.00 F
8	1		*Boot lid lock / <i>BT</i>	0.00	0.00	*80.00 F
9	1		*Rear bumper / <i>DD</i>	0.00	0.00	*220.00 F
10	1		*End panel / <i>DD</i>	0.00	0.00	*255.00 F
11	1		*Bonnet X R	0.00	0.00	*280.00 F
12	1		*Center grille / <i>CUT</i>	0.00	0.00	*210.00 F
13	1		*Center grille top chrome / <i>CUT</i>	0.00	0.00	*130.00 F
14	1		*Center grille logo badge / <i>nec</i>	0.00	0.00	*18.00 F
15	1		*Front bumper / <i>CR4</i>	0.00	0.00	*460.00 F
16	1		*Front bumper lower center grille / <i>CUT</i>	0.00	0.00	*120.00 F
17	1		*Front bumper towing cover / <i>CR4</i>	0.00	0.00	*13.00 F
18	1		*Front reinforcement / <i>DD</i>	0.00	0.00	*185.00 F
19	1		*Center grille lower chrome / <i>BR</i>	0.00	0.00	*130.00 F
20	1		*Rear bumper side retainer LH/RH@2*\$12 / <i>BR</i>	0.00	0.00	*24.00 F
21	1		*Rear bumper center garnish / <i>BR</i>	0.00	0.00	*50.00 F
22	1		*Rear bumper side fog cover LH/RH@2*\$20 / <i>CR4</i>	0.00	0.00	*40.00 F
23	1		*End panel top garnish / <i>CR4</i>	0.00	0.00	*48.00 F
24	1		*Tail lamp LH/RH@2*\$230 / <i>CUT</i>	0.00	0.00	*460.00 F
25	1		*Front bumper side retainer LH/RH@2*\$8 / <i>BR</i>	0.00	0.00	*16.00 F
26	1		*Front bumper lower headlamp bracket LH/RH@2*\$25 X	0.00	0.00	*50.00 F
27	1		*Headlamp LH/RH@2*\$445 X	0.00	0.00	*890.00 F
28	1		*Fog lamp cover LH/RH@2*\$28 (LH) / <i>BR</i> (RH) / <i>CUT</i>	0.00	0.00	*56.00 F
29	1		*Fog lamp cover top garnish LH/RH@2*\$17 (LH) / <i>CR4</i>	0.00	0.00	*34.00 F
30	1		*Rear floor panel (Repair refer to labour) X R	0.00	0.00	*- F
31	1		*Front support panel (Repair refer to labour) X R	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$\$) 4,699.00
+ Margin on L,N Items 10.00% (\$\$) 469.90
Total Parts (\$\$) 5,168.90

Wah Hong Motors & Credit Pte Ltd/SMJ4955L/01/12/2021 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Center grille clips <i>✓ nec</i>	35.00
2	1	End panel sealant <i>✓ nec</i>	60.00
3	1	Front bumper clips <i>✓ nec</i>	35.00
4	1	Front Car plate with holder <i>✓ AT</i>	35.00 ✓
5	1	Rear bumper clips <i>✓ nec</i>	35.00
6	1	Rear car plate with Holder <i>X</i>	35.00
7	1	Rear reverser sensor <i>✓ BR</i>	200.00
8	1	Rear windscreen sealant <i>✓ nec</i>	60.00
Sub Total (\$\$)			495.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,800.00 ✓
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,400.00 ✓
3	To perform anti-rust treatment on affected areas	New	40 60.00
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	30 60.00
5	To remove and refit rear compartment fitting, trimmings, garnish and etc	New	80 100.00
6	To remove and replace rear windscreen	New	100.00 ✓
Gross Labour Cost (\$\$)			3,520.00

Wah Hong Motors & Credit Pte Ltd/SMJ4955L/01/12/2021 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK) *WL PL*
2/12/21, 1.30pm *P/P*
My BoL sy
12 days

cost + 10% workshop provide invoice

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/12/2021 13:39 (SGT)
Date of Accident	30/11/2021 18:03 (SGT)
Exact Location of Accident	Near Thomson Flyover, Singapore
Additional Location Information	PIE TOWARDS CHANGI (THOMSON FLYOVER)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ4955L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	OOI JUN MING
NRIC No	SXXXX771Z
Email Address	TOOOT_KIA@HOTMAIL.COM
Mobile Phone No	(Phone) +65-93683984
Alternative Phone No	+65-93683984

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Fit
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1317

INSURANCE COMPANY

Name of Insurance Company	Etika Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MA013198
Cover Note Number	-

DRIVER

Name of Driver	LYE LI TENG CHERYL
NRIC No	SXXXX699D

Date Of Birth 26/02/1990
 Occupation Indoor
 Date Of Driving Pass 18/10/2010
 Driving experience 11 YEARS AND 1 MONTH
 Gender Female
 Mobile Number (Phone) +65-91826262
 Alt. Phone Number
 Email Address CHERYLLLT@HOTMAIL.COM
 Address BLK 194B BUKIT BATOK WEST AVENUE 6
 Address complement #05-237
 Postcode 652194
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Spouse
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 4
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Yes

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN FOR ACCIDENT DETAILS.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFM8628Y
 Vehicle Manufacturer Toyota
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver -
 Contact Number -
 Address -
 Address complement -

Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SFB2626A
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SBQ1838E
 Vehicle Manufacturer Audi
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid


8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



 Policyholder's Signature / Date &
 Time 1/12/2021 12:13pm


 Driver's Signature (if driver is not the policyholder) / Date
 & Time


 Witnessed by Reporting Centre
 Personnel

Sketch Plan

PIE TOWS CHANGI (THOMSON FLYOVER)



A - SMJ 4955L
 B - SFM 8628Y
 C - SFE 2626A
 D - SBQ 1838E

Describe Circumstances of the Accident


On 30/11/2021 @ 1803 HRS, I was driving my vehicle A (SMT 4955L) along the two lanes (Thames Flyover). Vehicle D (SBW 1838E) in front of my vehicle A (SMT 4955L) stopped and I stopped in time. Suddenly after a while, I felt a huge impact from the rear of my vehicle A (SMT 4955L). The impact forced my vehicle A (SMT 4955L) to move forward to collide with vehicle D (SBW 1838E). I stopped my vehicle A (SMT 4955L) and I felt pain on my neck and back. I alighted to do a check and realised that it was a chain collision. There were 3 more vehicles behind me involved in the accident.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	771Z
Vehicle Details	
Vehicle No.:	SMJ4955L
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Dec 2021
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3GF CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	L13B1449342
Chassis No.:	GK31341334
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$16,542.00
Original Registration Date:	08 Mar 2019
First Registration Date:	08 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$6,542.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Mar 2029
PARF Rebate Amount:	\$4,906.00
Intended COE Rebate Details	
COE Expiry Date:	07 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,170.00
COE Rebate Amount:	\$19,001.00
Total Rebate Amount:	\$23,907.00

The information contained herein is correct as at 01 Dec 2021

OK