

QUOTATION

Customer:

NO. : **39597**

AIG ASIA PACIFIC INSURANCE PTE LTD CHARTIS BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120

DATE : 01/12/2021 CLAIM NO. : 11826

ATTN: MOTOR CLAIMS DEPT

POLICY NO. : MC/00914724

FROM

: RAYMOND

VEHICLE NO.

: FBP6918E

MAKE/MODEL

: YAM / NMAX155 ABS

(Page 1 of 4)

<u>S/N</u>	<u>Description</u>	<u>Action</u>	Qty	<u>Unit Price</u>	<u>Amount</u>
1	BELLY PAN	REPLACE	1.00	\$35.00	35.00
	P/N: 58094				
	- (REPORTED BY MECHANIC)				
2	BOARD FOOTREST LH	REPLACE	1.00	\$55.00	55.00
	P/N: 59588				
	- (REPORTED BY MECHANIC)				
3	BOX FILTER AIR OUTER	REPLACE	1.00	\$18.00	18.00
	P/N: 58141				
	- (REPORTED BY MECHANIC)				
4	BOX FILTER AIR OUTER FRONT	REPLACE	1.00	\$10.00	10.00
	P/N: 58164				
	- (REPORTED BY MECHANIC)				
5	BUSH ENGINE	REPLACE	2.00	\$8.00	16.00
	P/N: 58144				
	- (REPORTED BY MECHANIC)				
6	CLIP NUT SPRING	REPLACE	5.00	\$1.50	7.50
	P/N: 59586				
_	- (REPORTED BY MECHANIC)	DEDI AGE		***	
7	COVER CLUTCH OUTER	REPLACE	1.00	\$66.00	66.00
	P/N: 58147				
•	- (REPORTED BY MECHANIC)	DEDLAGE	4.00	405.00	0.500
8	COVER FRONT (GREY)	REPLACE	1.00	\$35.00	35.00
	P/N: 63498 - (REPORTED BY MECHANIC)				
^	· · · · · · · · · · · · · · · · · · ·	DEDI ACE	4.00	# 00.00	00.00
9	COVER SIDE LH (MATTE BLACK)	REPLACE	1.00	\$38.00	38.00
	P/N: 66090 - (REPORTED BY MECHANIC)				
	- (IVEL OILLED DI MECHAMIC)				





Quotation Nos.: 39597 (Page 2 of 4)

<u>S/N</u>	Description	<u>Action</u>	Qty	<u>Unit Price</u>	<u>Amount</u>
10	COVER SIDE LOWER LH (BLUE) P/N: 60906	REPLACE	1.00	\$21.00	21.00
11	- (REPORTED BY MECHANIC) COVER SIDE REAR LH (BLUE) P/N: 60903	REPLACE	1.00	\$28.00	28.00
12	- (REPORTED BY MECHANIC) COVER SIDE REAR RH (GREY) P/N: 63495	REPLACE	1.00	\$28.00	28.00
13	- (REPORTED BY MECHANIC) COWLING FRONT LH (BLUE) P/N: 60912 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
14	DAMPER PLATE P/N: 64847 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	3.00
15	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	28.00
16	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	68.00
17	FOOTREST REAR ASSY 1 LH P/N: 58212 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
18	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$299.00	299.00
19	HOOK COVER SIDE P/N: 57086 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$1.50	6.00
20	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	10.00	\$63.00	630.00
21	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
22	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$223.00	223.00
23	LEVER BRAKE LH P/N: 58145	REPLACE	1.00	\$18.00	18.00
24	- (REPORTED BY MECHANIC) MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00





Quotation Nos.: 39597 (Page 3 of 4)

Quote	RIGHT 1403 GOODT				(i ago o oi i)
<u>S/N</u>	Description	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
25	MUDGUARD FRONT (GREY)	REPLACE	1.00	\$45.00	45.00
	P/N: 63496 - (REPORTED BY MECHANIC)				
26	MUDGUARD REAR	REPLACE	1.00	\$49.00	49.00
	P/N: 60932 - (REPORTED BY MECHANIC)				
27	PANEL 1 (MATTE BLACK) LH	REPLACE	1.00	\$21.00	21.00
	P/N: 63491 - (REPORTED BY MECHANIC)				
28	PLATE NUMBER REAR (6.5 INCH X 9 INCH)	REPLACE	1.00	\$28.00	28.00
	P/N: 26951 - (REPORTED BY MECHANIC)				
29	REFLECTOR REAR	REPLACE	2.00	\$4.50	9.00
	P/N: 67563 - (REPORTED BY MECHANIC)				
30	RIVET	REPLACE	12.00	\$3.00	36.00
	P/N: 56583 - (REPORTED BY MECHANIC)				
31	SCREW (VISOR)	REPLACE	4.00	\$3.00	12.00
	P/N: 62053 - (REPORTED BY MECHANIC)				
32	SEAT HANDLE (BLACK)	REPLACE	1.00	\$135.00	135.00
	P/N: 68460 - (REPORTED BY MECHANIC)				
33	SHAFT PIVOT	REPLACE	1.00	\$12.00	12.00
	P/N: 61967 - (REPORTED BY MECHANIC)				
34	SHOCK ABSORBER REAR	REPLACE	2.00	\$105.00	210.00
	P/N: 58133 - (REPORTED BY MECHANIC)				
35	STAND MAIN	REPLACE	1.00	\$63.00	63.00
	P/N: 58138 - (REPORTED BY MECHANIC)				
36	STICKER (MCDONALD) COVER SIDE	REPLACE	1.00	\$18.00	18.00
	P/N: 60256 - (REPORTED BY MECHANIC)				
37	STICKER (MCDONALDS) SIDE COVER / WINDSHEILD	REPLACE	1.00	\$16.00	16.00
	P/N: 56222 - (REPORTED BY MECHANIC)				
38	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	REPLACE	1.00	\$15.00	15.00
	P/N: 32921 - (REPORTED BY MECHANIC)				
39	STOPPER, MAIN STAND	REPLACE	1.00	\$7.00	7.00
	P/N: 61968 - (REPORTED BY MECHANIC)				





S/N	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
40	TRANSPORT CHARGES		1.00	\$50.00	50.00
	P/N: 07169				
	- BIKE TOWED BACK TO BHH				
41	WINDSHIELD	REPLACE	1.00	\$56.00	56.00
	P/N: 58073				
	- (REPORTED BY MECHANIC)				
		SUB TOTAL		_	\$2,547.50
		GST @ 7 %			\$178.33
		GRAND TOTAL (SG	D)		\$2,725.83

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.







Vehicle Details

Vehicle No. FBP6918E	Make / Model YAMAHA / NMAX155 ABS
Vehicle Type :	Vehicle Attachment 1 :
P01 - Passenger Scooter	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MH3SG431000011161
Propellant :	Engine No. :
Petrol	G3H6E0013884
Motor No. :	Engine Capacity :
-	155 cc
Power Rating:	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
295 kg	128 kg
Year Of Manufacture :	Original Registration Date :
2019	23 May 2019
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$3,602.00	22 May 2029
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
22 May 2022	-
Inspection Due Date :	Intended Transfer Date :
22 May 2022	03 Dec 2021
CO2 Emission :	CEV/VES Rebate Utilised Amount:
-	-
CO Emission :	HC Emission :



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue a

- A. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/11/2021 23:11 (SGT) Date of Accident 27/11/2021 19:35 (SGT) Exact Location of Accident Singapore Additional Location Information Telok kurau rd Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

FBP6918E

INSURED/POLICYHOLDER Is company? Name Of Registered Owner BAN HOCK HIN CO PTE LTD Company Reg No 1XXXXXX88K Email Address raymond@bhh.com.sg Mobile Phone No (Phone) +65-62816520 Alternative Phone No (Office) +65-62816520

VEHICLE PARTICULARS

Vehicle Registration Number

Manufacturer Yamaha NMAX155 ABS Model Exact purpose for which vehicle was being used at time of Private hire Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Motorcycle Transmission Manual CC 155

INSURANCE COMPANY

Direct Asia Insurance (Singapore) Pte Ltd Name of Insurance Company Type of Coverage ThirdParty Fleet Policy Yes Policy Number MC/00914724 Cover Note Number


DRIVER

RIDUWAN BIN ISMAIL Name of Driver NRIC No SXXXX307C

Date Of Birth 12/04/1971 Occupation Outdoor Date Of Driving Pass
Driving experience 11/12/1997 23 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-82071502 Alt. Phone Number Email Address raymond@bhh.com.sq 504 Bedok North Street 3 Address Address complement #14-112 Postcode 460504 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name Marine Parade Neighbourhood Police Centre Police Station Phone No (Phone) +65-18004428999 Alt. Police Station Phone No (Fax) +65-62447678 Police Station Address 300 Marine Parade Road Singapore 449296 Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO POLICE REPORT NO, T/20211127/2113 LODGE AT MARINE PARADE NPC
ON THE ABOVE MENTIONED DATE, TIME AND LOCATION, I WAS WORKING AS A MCDELIVERY RIDER, RIDING MY
MOTORCYCLE (FBP691E) ALONG TELOK KURAU ROAD. THE WASTHER WAS DRIZZLING AND THE TRAFFIC WAS SLOW
MOVING. I WAS QUEUING UP AT THE TRAFFIC BEFORE THE JUNCTION OF TELOK KURAU RD AND JOO CHIAT PI. I WAS STATIONARY WHEN A VEHICLE FROM BEHIND MADE CONTACT WITH MY MOTORCYCLE. I DID NOT FALL OFF MY BIKE. HOWEVER I GOT OFF AND MADE A CHECK AND NOTICED MY VEHICLE PLATE NUMBER DENTED. THE DRIVER OF THE SAID VEHICLE ALSO GOT OUT AND WE EXCHANGED PARTICULARS AND LEFT IN OUR SEPARATE WAYS. NO ONE WAS INJURED FROM THE INCIDENT. I INFORMED MY MANAGER ABOUT THE MATTER AND I WAS ASKED TO LODGE A POLICE REPORT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

No



Was there any audio recorded?

Vehicle Registration Number	SMA81G
Vehicle Manufacturer	Mercedes
Vehicle Model	Glc250
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Private car
Name of Driver	YAP KUAN SIANG
NRIC No	SXXXX295A
Contact Number	(Phone) +65-96664834
Address	_
Address complement	-
Postcode	_
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder) Date & Time: VERIFY BY AJAX MARS (ARC) REPORTING OFFICER MOHAMED SHARIL BIN SATAR


Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Comment William Francisco



SKETCH PLAN		
REFER TO ATTAC	CHED ACCIDENT DIAGRAM	
As police report	S OF THE ACCIDENT	
DECLARATION I/We declare the foregoing part	iculars are true in every respect.	VERIFY BY AJAX MARS (ARC) REPORTING OFFICER MOHAMED SHARIL BIN SATAR
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

2






Police Station Of Origin: Marine Parade N.P.C 300 Marine Parade Road SINGAPORE 449296 Tel No: 1800-4428999

Report No. T/20211127/2113

CONTINUATION OF REPORT

Rider Name	RIDUWAN BIN ISMAIL	12.7	ID No.	S711	2307C	
Related Vehicle			Contact No. Class of Driving Licence & Expiry Date		Class: 2B,3,4A Date of Expiry: NIL	
Hospital/Clinic						
Date Treatment No. of Days grant	NIL ted Medical Leave NIL	Date Disc Degree o				
Oriver Name	YAP KIAN SIANG (YE JIANXIAN	(G)	ID No.	\s	8106295A	
elated Vehicle	SMA81G (Car)		Contact I	9.01	96664834	
ospital/Clinic	NIL		Class of Driving Licence Expiry I	. &	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL nted Medical Leave NIL	Date D		VIL.		

On the above mentioned date, time and location, I was working as a McDelivery Rider, riding my motorcycle (FBP6918E) along Telok Kurau Rd. The weather was drizzling and the traffic was slow moving. I was queuing up at the traffic before the junction of Telok Kurau Rd and Joo Chiat Pl. I was stationary when a vehicle from behind mode. stationary when a vehicle from behind made contact with my motorcycle. I did not fall off my bike, however I got off and made a check and notice. however I got off and made a check and noticed my vehicle plate number dented. The driver of the said vehicle also got out and we exchanged portion. vehicle also got out and we exchanged particulars and left in our separate ways. No one was injured from the incident. I informed my manager about the the incident. I informed my manager about the matter and I was asked to lodge a police report.



INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SMA81G

Date of Accident

27/11/2021



Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance _____ AIG Asia Pacific Insurance Pte.... Period of Insurance ______26/06/2021 - 25/06/2022

Payment details

Request Amount: \$\$1.87 GST Amount: \$\$0.13

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: M400017735