



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JANICE			Ref: CC4/ASM21012233/Aga3q2 Date: 09/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3606S	Veh. Inspected	GBH 7998J
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03N8X	Excess (\$)	0.00
	Assign From		Assign Date	01/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	VM20127129	Colour	GREY
	Odometer	101547 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/70 R14	KAPSEN	6 mm
	L/H Front Tyre	185/70 R14	KAPSEN	6 mm
	R/H Rear Tyre	185/70 R14	KAPSEN	6 mm
	L/H Rear Tyre	185/70 R14	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/11/2021	Inspection Date	01/12/2021
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		24 Working Days	