

REF:

ASSIGNMENT

Veh No: GBF 8829Z Yr Regn: 2017 / Mar 01

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2582

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 138036 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JT FAT35Y 60K20128

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R 15C

R: 155R12C

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 86 mm	R/Bal. 96 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 02/12/21

Survey held at Kydes

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPA/g
	MV :
	PV :
	Nett:

☐: Prel. Report☐ : Final Report

Resurvey No. of Trip:

Transportation:

Add Fee: : Site Insp (\$

☐ : Site Insp (\$

S + RS	SI
--------	----

Report Format :

Interview

4 Photos

A constant $\sigma_{\text{eff}} = 1.0 \text{ eV}$

Tech. Inv. 19

1. *Why?*

Alfred 18
