



Your Ref: S1M03IWR

Date: 24<sup>th</sup> Jan 2021

Our Ref: CS3/ASM21010099/Evy3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way  
#24-01 Axa Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFU 5538B  
INSURED VEHICLE: SHA 9377D  
ACCIDENT DATE: 24/09/2021**

We thank you for your instruction on 02/12/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFU 5538B from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement and Police Report of Vehicle SFU 5538B.
- c) Colour damaged vehicle photographs of SFU 5538B.

Pre-Repair Inspection Date : 07/10/2021 at M/s V-Tech Auto Service, No.1 Soon Lee Street #06-04/05/06/07 Pioneer Centre, Singapore 627605.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SFU 5538B
Make & Model	: Nissan Sylphy 1.6 CVT ABS D/Airbag 2WD 4DR
Year of Registration	: 2014
Chassis Number	: MNTBBAB17Z0020661
Engine Capacity	: 1598 cc

- 2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.