NTUC (LBSUM)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.12.2021
Time: 08:58:15
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305496339
REGN NO	:	SHA2303M
MILEAGE	:	0000000000
MAKE	:	TOYOTA
MODEL	:	PRIUS HYBRID(G4)
DATE OF REGN	:	23.08.2017
DATE/TIME IN	:	01.12.2021 08:30
ACCIDENT DATE	:	30.11.2021

JOB / PARTS DESCRIPTION		QTY	IND UNIT-PRICE	DISC%	AMOUNT
PART REQUISITION					
0001 04-01-0302-0898-G	COVER OUTER MIRROR RH	1	141.90	25.00	106.42
0002 04-01-0302-0594-G	MIRROR ASSY OUTER REAR VI	1	1,390.10	25.00	1,042.57
				SUB-TOTAL :	1,148.99
JOB NATURE					
0000 PB	PANEL BEATING				150.00
0001 SP	SPRAYPAINT CHARGE				120.00
				SUB-TOTAL :	270.00
				TOTAL :	1,418.99

206.42

Jumani
MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE
DATE :

-20%: 150

1 Day
01/12/21
12pm
Case Qing
After repair photos

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: