

ASSIGNMENT

From: 120101
Estimated Cost: 1900017303
To inspect Vehicle No: 2140183711SG
of Workshop m/s
Insured:
Policy No.
Claims No.
Sum Insured:
(Gordon's Record)
Make of Vehicle
Excuse: 0

Sum Insured: _____ EXCESS: 0
(Client's Record)

Make of Vehicle

(Police Condition)

Remarks: The vehicle has been inspected and is ready for the time of inspection.

N/S	10/3

Prod. or Marking Values:		
ICAO Accident Report:	Consistent? : Yes or No	
GIA / PR Score:	Consistent? : Yes or No	
Est. Repairs:	days	Rev.: Yes or No
Cost Score:	%	3 Vol.: Yes or No

GA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle IN/OUT

Date / Yrs	Action / Instruction
	MV-70K

25/1/22 Final fig \$12,791 confirmed by email (red 4648, 26%)

<input type="checkbox"/>	Procl. Report
<input type="checkbox"/>	Final Report

27/1/22-typist

Merimen

www.pearsoned.com \$12,791

Vali No: SMJ 1769C YR: 25/2/19
Type: M. Car / M. cycle / Bus / Van / Lorry / Taxi / Private Mover /
Truck / Trailer or

Model: KIA Cerato C.B. 1541
Colour: White A/C: Insured 1/12/17/18

-Sp, Roosting 57836 Y/R: 60; Insured 1 St 1 Ni 1 N

Eng/No: . . .

Q.No: KNAF3416 MK 5009871
Q.No. Cond: Good / Fair / Poor / Buryt

Steering: Forward / Jammed / Locked / Burnt or
broken. Reverse / Jammed / Locked / Burnt or

Model 1 PHL / BIRMA / STO ARKIM OF

Tyre Size: P1 205/55R16
R1 11

BY/DUN/EXNOVA/GY/FS/LIZA/MIC/ORTSU/PIR/SOMI
YOYO/YOKO or Nexen

Front 12 mm Rear 4"

Ubal: 4 0:0:1 6/12/21

B.O.A. 5/12/12 Cycle & Carriage
Survey held at 8.00 / 0.15 / 11.15 / 1.00 / 2.00 / 3.00
of

Page 8 of 8

1

26%)

[Illegible handwritten notes]

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

Days of Repair: $\frac{12}{1}$ | Survey Fee: _____
Resurvey No. of Trips: $\frac{1}{1}$ | Transportation: _____

☐; Bitte Insp. (S. _____) S. 10

Interview	(S)	_____	Views	_____
Techn. Insp	(M)	_____		_____
	(H)	_____		_____

1996 11/16/96 11:16 AM 11/16/96 11:16 AM 11/16/96 11:16 AM

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/Chua Teck Yong, Daniel (cai Der</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ1769C / 25/02/201</td></tr> <tr> <td>Date In/Mileage</td><td>04/12/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5009871</td></tr> <tr> <td>Engine No</td><td>G4FGJH702498</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Chua Teck Yong, Daniel (cai Der	Reg No/Reg Date	SMJ1769C / 25/02/201	Date In/Mileage	04/12/2021/ 0	Chassis No	KNAF3416MK5009871	Engine No	G4FGJH702498	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/Chua Teck Yong, Daniel (cai Der														
Reg No/Reg Date	SMJ1769C / 25/02/201														
Date In/Mileage	04/12/2021/ 0														
Chassis No	KNAF3416MK5009871														
Engine No	G4FGJH702498														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	04/12/2021/ 11:42	BLK	282 / Kevin Leong	43394			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3600.00
REPLACE REAR BUMPER, BOOT, END PANEL, SPARE TYRE PANEL, REAR LH FENDER					5 x 400			2000
REAR LH HEADLAMP PANEL & AFFECTED AREA								
E PNT98000								2100.00
PAINT WORK ON REAR BUMPER, BOOT, END PANEL, SPARE TYRE PANEL,					5 x 350			1750
REAR LH FENDER & LH TAIL LAMP PANEL								80.00
E PNT88000								120.00
REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR								120.00
E PNT88000								120.00
TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								120.00
E PNT88000								240.00
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								X 240.00
E PNT88000								80.00
REMOVE & REPLACE REAR WINDSCREEN GLASS								X 80.00
M SUNDRY								220.00
TO APPLY WINDSCREEN SEALANT								X 220.00
M SUNDRY								120.00
TO SUPPLY WINDSCREEN SOLAR FILM								120.00
E PNT88000								400.00
TO TRANSFER BOOT COMPARTMENT TO NEW PANEL								X 400.00
A 13900099								120.00
REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR								80 120.00
M SUNDRY								80.00
TO APPLY SEALANT ON AFFECTED AREA								40 80.00
M SUNDRY								30.00
PERFORM RUST PREVENTION								30.00
A 54900099								120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901								50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								50.00
M SUNDRY								50.00
TO SUPPLY REAR NUMBER PLATE WITH FRAME								20 50.00
M SUNDRY								50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Chua Teck Yong, Daniel (cai Der Reg No/Reg Date SMJ1769C / 25/02/201 Date In/Mileage 04/12/2021/ 0 Chassis No KNAF3416MK5009871 Engine No G4FGJH702498 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	04/12/2021/ 11:42	BLK	282 / Kevin Leong	43394			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO SUPPLY C & C EMBLEM					1.00	675.00	20.00	540.00
M	LAMP ASSY-REAR COMB OUTSIDE,LH	BR			1.00	675.00	20.00	540.00
M	LAMP ASSY-REAR COMB OUTSIDE,RH	CUT			1.00	608.00	20.00	486.40
M	LAMP ASSY-REAR COMB INSIDE,LH	BR			1.00	608.00	20.00	486.40
M	LAMP ASSY-REAR COMB INSIDE,RH	BR			1.00	690.00	20.00	552.00
M	LAMP ASSY-CENTER GARNISH	BR			1.00	324.00	20.00	259.20
M	PANEL ASSY-BACK	DD			1.00	1297.00	20.00	1037.60
M	PANEL ASSY-TRUNK LID	DD			1.00	97.00	20.00	77.60
M	HINGE ASSY-TRUNK LID,LH	BT			1.00	97.00	20.00	77.60
M	HINGE ASSY-TRUNK LID,RH	BT			1.00	312.00	20.00	249.60
M	PANEL & FRAME ASSY-PKG TRAY,RR	?			1.00	219.00	20.00	175.20
M	PANEL ASSY-REAR FLOOR,RR	?			1.00	1349.00	20.00	1079.20
M	PANEL ASSY-QUARTER OUTER,LH	X			1.00	139.00	20.00	111.20
M	PANEL ASSY-RR COMB LAMP HSG,LH	DD			1.00	211.00	20.00	168.80
M	MAT ASSY-LUGGAGE COVERING	?			1.00	41.00	20.00	32.80
M	TRIM ASSY-RR TRANSVERSE	CRU			1.00	447.00	20.00	357.60
M	GLASS ASSY-REAR WINDOW	X			10.00	2.00	20.00	16.00
M	PAD-WINDSHIELD GLASS	X			2.00	4.00	20.00	6.40
M	STOPPER-GLASS	X			4.00	4.00	20.00	12.80
M	TERMINAL-RR WDO GLASS DEFOGGER	X			1.00	28.00	20.00	22.40
M	EMBLEM-CERATO	REC			1.00	32.00	20.00	25.60
M	LOGO ASSY-KIA SUB	MC			1.00	33.00	20.00	26.40
M	COVER-RR BUMPER UNDER,LH	BR			1.00	241.00	20.00	192.80
M	COVER-RR BUMPER LWR	BR			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER	BR			1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP,LH	CUT			1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP,RH	CUT			1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL,LH	?			1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL,RH	?			1.00	207.00	20.00	165.60
M	EXTN WIRING ASSY-BWS	?			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG,LH	?			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG,RH	?			1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR,CTR	CRU						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

Co Reg No : 199405410K

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/Chua Teck Yong, Daniel (cai Der</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ1769C / 25/02/201</td></tr> <tr> <td>Date In/Mileage</td><td>04/12/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5009871</td></tr> <tr> <td>Engine No</td><td>G4FGJH702498</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Chua Teck Yong, Daniel (cai Der	Reg No/Reg Date	SMJ1769C / 25/02/201	Date In/Mileage	04/12/2021/ 0	Chassis No	KNAF3416MK5009871	Engine No	G4FGJH702498	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/Chua Teck Yong, Daniel (cai Der														
Reg No/Reg Date	SMJ1769C / 25/02/201														
Date In/Mileage	04/12/2021/ 0														
Chassis No	KNAF3416MK5009871														
Engine No	G4FGJH702498														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

					WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator				
LAX00000	Credit	04/12/2021/ 11:42	BLK	282 / Kevin Leong	43394			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM LWR MTG	✓	CKU		1.00	6.00	20.00	4.80
M	BEAM-RR BUMPER	✓	BR		1.00	318.00	20.00	254.40
M	ANTENNA ASSY-SMARTKEY				1.00	46.00	20.00	36.80
M	STAY-RR BUMPER LH	✓	OO		1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH	✓	OO		1.00	65.00	20.00	52.00
M	BRACKET ASSY-RR BPR SIDE UPR,L	✓	BR		1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR,R	✓	BR		1.00	31.00	20.00	24.80

Estimate

Steve CLKK)
6/12/21, 2:00pm

OR- H/L AL
Excess - ?
P/P
My Bel sy
9 dgr

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by
Signature:
Date:

	Nett	15,534.00
7% GST on	15534.00	1087.38
Total Payable		16,621.38

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/12/2021 09:27 (SGT)
Date of Accident	03/12/2021 17:12 (SGT)
Exact Location of Accident	Seletar West Link, Singapore
Additional Location Information	SELETAR WEST LINK TO YISHUN AVENUE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ1769C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHUA TECK YONG, DANIEL (CAI DERONG, DANIEL)
NRIC No	SXXXX649I
Email Address	dcheroes02@gmail.com
Mobile Phone No	(Phone) +65-91167702
Alternative Phone No	+65-91167702

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900017303-01
Cover Note Number	-

DRIVER

Name of Driver	CHUA TECK YONG, DANIEL (CAI DERONG, DANIEL)
NRIC No	SXXXX649I

Date Of Birth	11/02/1980
Occupation	Indoor
Date Of Driving Pass	20/12/2006
Driving experience	15 YEARS
Gender	Male
Mobile Number	(Phone) +65-91167702
Alt. Phone Number	+65-91167702
Email Address	dcheroes02@gmail.com
Address	BLK. 14 YISHUN AVENUE 9
Address complement	#05-16 SINGAPORE
Postcode	768895
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	No
Does Driver Own Other Vehicles?	-
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW3443G
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	SHANMUGAM KANNAN
Contact Number	(Phone) +65-94882399
Address	-
Address complement	-

Insurance Code
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident

Vehicle (Taxi) breakdown at left lane and display a triangle breakdown plate at road. I stopped my vehicle, signal right to filter into the second lane. Then all at sudden mini-lorry (Pickup) (G-W 34436) hit my vehicle from the rear.


Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder
Period of Insurance
Engine No.
Chassis No.

: CHUA TECK YONG, DANIEL (CAI DERONG, DANIEL)
: 25 Feb 2021 To 24 Feb 2022
: G4FGJH702498
: KNAF3416MK5009871

Vehicle No. : SMJ1769C
Policy No. : 1900017303-01
Endorsement No. : 000000000400604
Issued Date : 18 Jun 2021

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAFF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Mileage Condition : Unlimited Mileage

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHUA TECK YONG, DANIEL (CAI DERONG, DANIEL) - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622204

C&CKICP2 - CTEAS

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPCPH

1004564308/AC1