

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 04.12.2021
 Emailed : 11.01.2022, 11.30am
 Date Survey : 06.12.2021

VEHICLE NO : SKG 6661 K
 MODEL : KIA SORENTO 2.4 A
 WIP : 43420

Material	:	\$	<u>3,657.60</u>
Labour	:	\$	<u>3,330.00</u>
Sub-Total	:	\$	<u>6,987.60</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>6,987.60</u>
GST 7%	:	\$	<u>489.13</u>
Grand Total	:	\$	<u>7,476.73</u>
Finalise By/Date	:	<u>LOI / 11/01/2022</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12241/MR PEK BAN HUA Reg No/Reg Date SKG6661K / 20/03/2020 Date In/Mileage 08/12/2021/ 20067 Chassis/Package KNAPH813ML5636133 /# Engine No G4KJKH776008 Make/Model KIA/SORENTO 2.4 A SX GDI SR Colour/Trim KLG STEEL GREY / WK SATURN BLACK
08/12/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/01/2022/ 11:28	BLE	260 / AiTing	43420

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH FRONT DOOR, LH REAR DOOR, REPAIR LH CENTRE PILLAR PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				1200.00
E PNT98000 RESPRAY ON LH FRONT DOOR, LH REAR DOOR, LH CENTRE PILLAR, AND ALL OTHER AFFECTED AREAS TO THE SAME				1050.00
E PNT88000 REMOVE & REINSTALL LH FRONT DOOR COMPONENTS TO NEW PANEL				120.00
E PNT88000 REMOVE & REINSTALL LH REAR DOOR COMPONENTS TO NEW PANEL				120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				120.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
A 34900099 REPLACE LH REAR UNDERCARRIAGE PARTS				400.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY SUPPLY BODY PANEL SEALANT				80.00
M SUNDRY SUNDRIES				20.00
S SPECIALISTJOB REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALVE, AND CONDUCT WHEEL BALANCING				30.00
X PANEL ASSY-FRONT DOOR,LH	1.00	1582.00	20.00	1265.60
X GARNISH ASSY-FRT DR SIDE,LH	1.00	204.00	20.00	163.20
X GARNISH ASSY-RR DR SIDE LH	1.00	242.00	20.00	193.60
X MOULDING ASSY-SIDE SILL,LH	1.00	141.00	20.00	112.80
X PANEL ASSY-REAR DOOR,LH	1.00	1290.00	20.00	1032.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 08/12/2021	<table> <tr> <td>Cust No/Name</td><td>LCV12241/MR PEK BAN HUA</td></tr> <tr> <td>Reg No/Reg Date</td><td>SKG6661K / 20/03/2020</td></tr> <tr> <td>Date In/Mileage</td><td>08/12/2021/ 20067</td></tr> <tr> <td>Chassis/Package</td><td>KNAPH813ML5636133 /#</td></tr> <tr> <td>Engine No</td><td>G4KJKH776008</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.4 A SX GDI SR</td></tr> <tr> <td>Colour/Trim</td><td>KLG STEEL GREY / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV12241/MR PEK BAN HUA	Reg No/Reg Date	SKG6661K / 20/03/2020	Date In/Mileage	08/12/2021/ 20067	Chassis/Package	KNAPH813ML5636133 /#	Engine No	G4KJKH776008	Make/Model	KIA/SORENTO 2.4 A SX GDI SR	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK
Cust No/Name	LCV12241/MR PEK BAN HUA														
Reg No/Reg Date	SKG6661K / 20/03/2020														
Date In/Mileage	08/12/2021/ 20067														
Chassis/Package	KNAPH813ML5636133 /#														
Engine No	G4KJKH776008														
Make/Model	KIA/SORENTO 2.4 A SX GDI SR														
Colour/Trim	KLG STEEL GREY / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/01/2022/ 11:28	BLE	260 / AiTing	43420

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X WHEEL ASSY-ALUMINIUM LHR	1.00	689.00	20.00	551.20
X ARM & BUSH ASSY-SUSP UPR	1.00	159.00	20.00	127.20
X ARM ASSY-RR ASSIST	1.00	240.00	20.00	192.00
X BOLT → Supp	1.00	14.00	20.00	11.20
X FILM-RR DR ANTI CHIPPING,LH	1.00	11.00	20.00	8.80

Z TEXT

AIG OD CLAIM.

DOA: 04.12.21

SURVEYOR STEVE LKK 06.12.21

POLICY NO : 2070052758 REPAIR 16 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,657.60		Nett	6,987.60
Labour	3,160.00	7% GST on	6987.60	489.13
Standard Menu	0.00			
Specialist Job	30.00			
Diagnostics Job	0.00		Total Payable	7,476.73
Sundry/Others	140.00			
Total(w/o GST)	6,987.60			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SKG 6661 K

<u>Materials</u>		<u>Cost (\$)</u>
1	Bolt	14.00 - BT

Total		14.00
Less 20% discount		2.80

Total after discount		11.20
7% GST		0.78

Grand total		<u>11.98</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SKG6661K

WIP: 43420

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	ABSORBER LHR - 5531065200-1	? / SUPP	JF		
2	R.R. Arm Assist LH - 5525065050-1	? / SUPP	JF		
3	Arm Assist Bolt - 626173K200-1	? / SUPP	JF		
4	Arm Assist Assy - Susp wpr - 5510065050	? / SUPP	JF		
5		? / SUPP			
6	LHR Door King Low	? / SUPP			
7	LHR Door Firm	? / SUPP	JF		
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: SORENTO

SURVEYOR: STEVE

Work Order: R001593
 License: skg 6661 k
 Technician: kfsan 810119
 Mileage: 20068
 Date: 13.12.21 11:06

Kia : Sorento : 2015-20 (UM/UMA) : Front Wheel Drive : Rest of World

Front : Left

Actual	Before	Specified Range
-0°42'	-0°42'	-1°00' 0°00'
3°55'	3°55'	3°53' 4°53'
0°02'	-0°01'	-0°03' 0°09'
10°32'*	10°32'*	12°50' 13°50'
9°50'*	9°50'*	11°50' 13°50'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°42'	-0°46'	-1°00' 0°00'
4°42'	4°42'	3°53' 4°53'
0°02'	0°04'	-0°03' 0°09'
12°03'*	12°06'*	12°50' 13°50'
11°21'*	11°21'*	11°50' 13°50'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°01'	0°04'	
-0°47'	-0°47'	
-1°32'	-1°35'	
0°03'	0°02'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°07'	-1°02'	-1°30' -0°30'
0°07'	0°01'	0°00' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°59'	-0°35'	-1°30' -0°30'
0°02'	-0°08'*	0°00' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°08'	-0°27'	
0°09'	-0°07'*	0°00' 0°24'
0°03'	0°05'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



SORENTO(UM)/2020/G 2.4 GDI..

VCI




Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



19/19

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESP	No Current DTC	Good
EPB	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0261

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0200

OS Ver.

Android 10