

PRS

ASSIGNMENT


13/06/2018

From: _____ Date: _____
 Estimated Cost: _____
 QD TP / S / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: BIKES AND TEA
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: FBN173L Yr Regn: - /
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HONDA CB150R c.c. 149
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MLHKC2881J5017025 *
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / R / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$9000
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 110/70-17
 R: 140/70-17
 BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 07-12-2021
 Survey held at _____ W/S 12:30PM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$3000 - \$4000
	submit PRS Report

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?
 2) _____
 Report Filed?
 Long Copy / MP/...

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Insp (\$ _____)
 : Wheel end (\$ _____)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	