



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT21003732	<b>Page</b>	1
<b>Registration No</b>	: SMX4583C	<b>Date</b>	: 3. Dec 2021	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRU1810JX202844	<b>Svc Advisor</b>	: SUHELMI	<b>Engine No</b>	: L15B5672852
<b>Model</b>	: HRV DX-SIN CVT YM 2018	<b>Date   Time</b>	: 3. Dec 2021 9:10:52 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: CHANG KUAN LIAN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 2/12/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: CHANG KUAN LIAN OWNER INSURER: TOKIO MARINE ACC DATE: 02/12/2021 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: GBH9396H						
04646-T7A-310ZZ	PANEL SET,L.RR.OUTSIDE	1	655.20	25	491.40	34.40	525.80
67550-T7A-305ZZ	PANEL COMP,L.RR.DOOR	1	935.10	25	701.32	49.09	750.41
67865-T7A-003	TAPEL.RR.DOOR SASH	1	21.00	25	15.75	1.10	16.85
75895-T7A-003	TAPEL.RR.DOOR PROTECTION	1	25.70	25	19.27	1.35	20.62
72864-T7A-003	SUB SEALL.RR.DOOR RR.	1	8.70	25	6.52	0.46	6.98
72866-T7A-J01	SEALL.DOOR LOWER	1	5.90	25	4.42	0.31	4.73
72865-T7A-003	SUB SEALL.RR.DOOR CENTER	1	46.80	25	35.10	2.46	37.56
72650-T0A-H01	LATCH ASSYL.RR.DOOR	1	212.90	25	159.67	11.18	170.85
72652-T0A-A01	CAPL.CHILD LOCK	1	3.90	25	2.92	0.20	3.12
72875-T7A-003	WEATHERSTRIPL.RR.DOOR OUTER	1	23.00	25	17.25	1.21	18.46
72950-T7A-003	MOLDING ASSYL.RR.DOOR	1	47.80	25	35.85	2.51	38.36
72450-T7A-003	MOLDING ASSYL.FR.DOOR	1	27.00	25	20.25	1.42	21.67
71850-T7B-013	GARNISH ASSY,L.SIDE	1	402.60	25	301.95	21.14	323.09
71851-T7J-H01	PROTECTION TAPE,L.SILL	1	22.10	25	16.57	1.16	17.73
74450-T7B-003	PROTECTOR,L.RR.WHEEL ARCH	1	187.20	25	140.40	9.83	150.23
74592-T7A-010	FENDERL.RR.INNER	1	98.40	25	73.80	5.17	78.97
91501-T2A-003	CLIPINNER FENDER	4	0.40	25	1.20	0.08	1.28
72750-T7A-003	REGULATOR ASSYL.RR.DOOR	1	393.10	25	294.82	20.64	315.46
42700-T7A-J92	DISK,ALUMINIUM WHEEL	1	833.00	25	624.75	43.73	668.48

Printed on 3/12/2021 10:20:14 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT21003732	<b>Page</b>	2
<b>Registration No</b>	: SMX4583C	<b>Date</b>	: 3. Dec 2021	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRU1810JX202844	<b>Svc Advisor</b>	: SUHELMI	<b>Engine No</b>	: L15B5672852
<b>Model</b>	: HRV DX-SIN CVT YM 2018	<b>Date   Time</b>	: 3. Dec 2021 9:10:52 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: CHANG KUAN LIAN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 2/12/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
					<b>Sum Item</b>	<b>2963.21</b>	<b>207.44</b>	<b>3,170.65</b>
<b>BO-WHEEL ALIGN X4</b>	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60	
					<b>Sum Ext. Service</b>	<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
<b>BOSUN</b>	SUNDRIES	1	50.00		50.00	3.50	53.50	
<b>BML02I</b>	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60	
<b>BOJSE</b>	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00	
<b>BOBC</b>	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00	
<b>BP00R</b>	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50	
<b>BA02R</b>	REMOVE & RENEW INSTALL SENSORS-4 PCS (N)	1	200.00		200.00	14.00	214.00	
<b>BKDR21R</b>	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	650.00		650.00	45.50	695.50	
<b>BMI03D</b>	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50	
<b>BC012R</b>	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50	
<b>BMF00D</b>	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	450.00		450.00	31.50	481.50	
<b>BMI02D</b>	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	450.00		450.00	31.50	481.50	
<b>BKFE21R</b>	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL	1	4200.00		4200.00	294.00	4494.00	
<b>BP05R</b>	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00		2800.00	196.00	2996.00	
					<b>Sum Labor</b>	<b>10330.00</b>	<b>723.10</b>	<b>11,053.10</b>

Survey By \_\_\_\_\_  
Date & Time \_\_\_\_\_  
Excess \_\_\_\_\_  
Status \_\_\_\_\_  
Signature \_\_\_\_\_

**Total Amount** 13,473.21 943.14 **14,416.35**  
**Total (Inclusive of GST)** **14,416.35**

Printed on 3/12/2021 10:20:14 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	02/12/2021 17:07 (SGT)
Date of Accident	02/12/2021 08:10 (SGT)
Exact Location of Accident	Near 56 W Coast Cres, Singapore 128038
Additional Location Information	WEST COAST LINK TO WEST COAST ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SMX4583C

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHANG KUAN LIAN
NRIC No	SXXXX654H
Email Address	kuanlian_chang@gmail.com
Mobile Phone No	(Phone) +65-90086116
Alternative Phone No	+65-90086116

### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Hr-v
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

### INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

### DRIVER

Name of Driver	CHANG KUAN LIAN
NRIC No	SXXXX654H

Date Of Birth	18/12/1979
Occupation	Indoor
Date Of Driving Pass	28/09/2009
Driving experience	12 YEARS AND 3 MONTHS
Gender	Female
Mobile Number	(Phone) +65-90086116
Alt. Phone Number	+65-90086116
Email Address	kuanlian_chang@gmail.com
Address	307C ANG MO KIO AVE 1
Address complement	05-455
Postcode	563307
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	BONG TONG HSIA
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9396H
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	RENE TAN SOO HOW
Contact Number	(Phone) +65-94879079
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


Vehicle

Number: 9MX45836

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:


2/12/2021

\_\_\_\_\_  
 Driver's Signature (If driver is not the policyholder)  
 Date & Time:

  
 Report Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Vehicle Number: SMX 9583L

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving from West Coast Link and turned right to West Coast Road at T-junction after traffic light turned green. And, I felt the impact at the left side of my car. I was knocked by another car.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature (If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NOC/IN No.: