

Steve CS/AIG/2012339/EF3

ASSIGNMENT

From: 120101

Estimated Cost

ON/INS/REG/OD/REG/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Claim No. 8974278496SG

Sum Insured: Excess: 300

(Citizen's Record)

Makes of Veh:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Dist. or Market Value:

IOAC Accident Report Consistent? Yes or No

SIA / PR Seen Consistent? Yes or No

Est. Repairs: 10 days Rep: Yes or No

Loss Sum: % 3 Vol: Yes or No

QA / REV / REP. / 24 HRS

Date: Person Contacted:

Calls / Vms: Action / Instruction

Veh No: SMG15362 YR Reg: 6/12/18

Type: M/Cycle / Bus / Van / Lorry / Taxi / Private Motor

Truck / Trailer or

Make: Mitsubishi Attrage

Colour: White

Sp/Recording: 63846

Eng/No:

Chassis: MMBSTA13A7H004307

Gen. Condi: Good / Fair / Poor / Bught

Steering: Locked / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: H11 / 3/11m / 3/10 A/Rim or

Tyre Size: P1 185/55R15

RI

BY: SUN / EXNOVA / GY / FS / LIZA / MIG / OHTIV / PIR / SUMI /

YOYO / YOKO or

Front: 5 mm

Rear: 5 mm

Left: 5 mm

Right: 5 mm

D.O.A. 4/12/21

Survey held at: Cycle & Carriage

Des. of Damages: Front / Rear / O/S / H/S / B/C / Reelap or

The V/O / Chassis / Frame / Body Structure affected due to collision

07/12/21@4.16pm revert to AIG via Merimen.

07/12/21@7.15pm Kok Chong informed C/A via Merimen.

08/12/21@9.18am Informed Kevin C/A & ex: \$300 by email.

26/01/22@10.06am confirmed with Ms Loi final fig \$12450.37, 10 days. (Red \$3281.28, 21%)

Time/Date, File Reference: ☐ Prelim. Report ☐ Final Report

Time/Date, File Reference:

Days of Repairs: 10

Resurvey No. of Trips: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Vehicle Insp (\$)

Survey Fee: ☐ Transportation ☐ SERS ☐ Penalties ☐ Others

MER-OD 12450.37



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAY NGAK MONG
	Reg No/Reg Date	SMG1536Z / 06/12/201
	Date In/Mileage	06/12/2021/ 0
	Chassis No	MMBSTA13AJH004307
	Engine No	3A92UHK0272
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	07/12/2021/ 13:32	BLK	282 / Kevin Leong	18249			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2025 3600.00
REPLACE FRT BUMPER, BONNET, SUPPORT, FRT RH FENDER & AFFECTED AREA 4.5 X								
REPAIR ON FRT LH FENDER & FRT BOTH BODY CHASSIS								2100 2800.00
E PNT98000								
PAINT WORK ON FRT BUMPER, BONNET, SUPPORT, BOTH FRT BODY CHASSIS, 6 X 350								
2 BOTH FRT FENDER & BODY KIT (RH lower spoke)								120.00
E PNT88000								80.00
REMOVE & REPLACE RADIATOR, CONDENSER FOR FACILITATE REPAIR								80.00
A 55900099								80.00
TO TOP UP AIRCON GAS								
E PNT88000								40 80.00
REMOVE & INSTALL BODY KIT FOR FACILITATE REPAIR								
M SUNDRY								40 80.00
PERFORM RUST PREVENTION								
M SUNDRY								50.00
TO APPLY SEALANT ON AFFECTED AREA								
M SUNDRY								70 50.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME								
M SUNDRY								
SUNDRIES								
S SPECIALISTJOB								
WO: 1275091 ACCIDENT TOWED FROM WOODLAND AVE1 TO CNC PG								
Date 4/12/21(Sat); Time Start 18.13; Time End 19.30pm								
Normal Towing \$50; Add: Accident \$10								
Total Cost \$60								
M EMBLEM ECO					2.00	17.00	00.00	34.00
M HEADLAMP ASSY, LH					1.00	663.00	23.00	510.51
M HEADLAMP ASSY, RH					1.00	663.00	23.00	510.51
M TANK, WINDSHIELD WASHER					1.00	75.00	23.00	57.75
M HORN					1.00	79.00	23.00	60.83
M CONDENSER ASSY, A/C REFRIGE					1.00	762.00	23.00	586.74
M RADIATOR ASSY					1.00	972.00	23.00	748.44
M PANEL, AIR GUIDE					1.00	112.00	23.00	86.24

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAY NGAK MONG Reg No/Reg Date SMG1536Z / 06/12/201 Date In/Mileage 06/12/2021/ 0 Chassis No MMBSTA13AJH004307 Engine No 3A92UHK0272 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	07/12/2021/ 13:32	BLK	282 / Kevin Leong	18249		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	SHROUD, COOLING FAN	BR		1.00	131.00	23.00	100.87
M	FAN, COOLING, LH	?		1.00	77.00	23.00	59.29
M	TANK ASSY, RADIATOR	COND		1.00	42.00	23.00	32.34
M	MOTOR, COOLING FAN	?		1.00	484.00	23.00	372.68
M	DUCT, A/CLNR INTAKE	OR		1.00	131.00	23.00	100.87
M	FACE, FR BUMPER	OR		1.00	706.00	23.00	543.62
M	GRILLE, RADIATOR	OR		1.00	557.00	23.00	428.89
M	AIR DAM, SIDE, FR RH	?		1.00	18.00	23.00	13.86
M	AIR DAM, SIDE, FR LH	?		1.00	18.00	23.00	13.86
M	GRILLE, FR UNDER	OR		1.00	165.00	23.00	127.05
M	BRACKET, FR BUMPER, RH	OR		1.00	13.00	23.00	10.01
M	BRACKET, FR BUMPER, LH	OR		1.00	13.00	23.00	10.01
M	COVER, HEADLAMP SUPT PANEL	BR		1.00	62.00	23.00	47.74
M	MARK, THREE-DIA	nec		1.00	70.00	23.00	53.90
M	HOOD	OR		1.00	737.00	23.00	567.49
M	INSULATOR, HOOD	CR4		1.00	177.00	23.00	136.29
M	HINGE, HOOD, LH	OT		1.00	56.00	23.00	43.12
M	HINGE, HOOD, RH	OT		1.00	56.00	23.00	43.12
M	DAM, HOOD	?		1.00	20.00	23.00	15.40
M	WEATHERSTRIP, HOOD, RR	?		1.00	51.00	23.00	39.27
M	FENDER, FR RH	OR		1.00	500.00	23.00	385.00
M	PANEL ASSY, FR END	OR		1.00	1055.00	23.00	812.35
M	PANEL, HEADLAMP SUPPORT, UPR	OR		1.00	66.00	23.00	50.82
M	COVER, ENG ROOM UNDER, FR	?		1.00	99.00	23.00	76.23
M	SHIELD, FR WHEELHOUSE, RH	?		1.00	98.00	23.00	75.46
M	COVER, FR DECK, RH	OR		1.00	16.00	23.00	12.32
M	GARNISH, FR DECK	?		1.00	178.00	23.00	137.06
M	UNPAINTED BODYKITS	BR (RH lower Spiller)		1.00	1643.00	20.00	1314.40

Estimate

Stev (LKK)
7/12/21, 1:32pm

OD-M-1 AL
Excess-?
P/P

LKK Auto Consultants hence notify
the Remains of the following

Estimate

Stew (LKK)
7/12/21, 1:30pmOD-M1 AL
Excess-?
P/P

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairs of the following:

- No warranty on damaged parts during survey
- Parts prices are subject to confirmation
- This party survey is on "top-out" basis
- No unapproved alterations allowed
- Supplementary parts to be fitted to damaged part is subject to final approval from our company

Authorized signatory and company stamp

10 days, My Bel Sy

Nett	15,158.34
7% GST on	1061.08
Total Payable	16,219.42

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/12/2021 16:55 (SGT)
Date of Accident	04/12/2021 16:44 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TO CHANGI, BEFORE KIM KEAT FLYOVER
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG1536Z

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAY NGAK MONG
NRIC No	SXXXX471I
Email Address	JC.CHUALC@GMAIL.COM
Mobile Phone No	(Phone) +65-97257937
Alternative Phone No	+65-98314409

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1193

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800144741-01
Cover Note Number	-

DRIVER

Name of Driver	ALOYSIUS TAY HUI MING
NRIC No	SXXXX719E

Date Of Birth	10/11/1998
Occupation	Indoor
Date Of Driving Pass	08/11/2017
Driving experience	4 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-98314409
Alt. Phone Number	-
Email Address	ALOYSIUS.TAYHM@GMAIL.COM
Address	369 WOODLANDS AVENUE 1 #09-861
Address complement	-
Postcode	730369
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

PASSENGER 1

Name	CHARMAINE CHIA XIE MIN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tanglin Division Headquarters
Police Station Phone No	(Phone) +65-18003910000
Alt. Police Station Phone No	(Fax) +65-63964900
Police Station Address	21 Kampong Java Road Singapore 228892
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EV3778U
Vehicle Manufacturer	BMW

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ALOYSIUS TAY HUI MING
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	CLOSED FRACTURE OF ANKLE
Injured person in which vehicle?	SMG1536Z
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

PIE towards Changi, before Kim Keat Flyover



A - SMG 1536 Z
B - EV 3778 U

Describe Circumstances of the Accident

2021
On 4th Dec 16:44 hrs, I was travelling on PIE towards Changi, before Kimkeat Flyover when suddenly car B which was in front of A, jammed the brake.
Car A immediately stopped the brake and car rolled forward and hit car B in
within a few moments, before I alighted my car, two total of 4 people (incl car B driver) approached me with a namecard for his workshop and asked me to go to his workshop
2 passengers, including driver was on car B.
Another 2, was from another car which was parked at road shoulder even before accident happen.

Declaration


We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



SINGAPORE POLICE FORCE



E/20211206/7017

1 of 2

POLICE REPORT (NP299)

Report No. E/20211206/7017

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-3910000

Date/Time Report Made 06/12/2021 13:13	Vide Report No.		Station Diary No.	
Name Of Informant ALOYSIUS TAY HUI MING	Address 369 WOODLANDS AVENUE 1 #09-861 SINGAPORE 730369			
ID Type / ID No. NRIC NO / S9836719E	Contact No. Home/Office:		Mobile: 98314409	
Nationality SINGAPORE CITIZEN	Email Address ALOYSIUS.TAYHM@GMAIL.COM			
Occupation	Sex Male	Age 23	Date of Birth 10/11/1998	Race Chinese
National Service Full Time Institution/School Name	Language English			
Date/Time Of Incident 04/12/2021 16:45 - 04/12/2021 16:55	Location Of Incident PAN ISLAND EXPRESSWAY			

Brief details.

I was driving on the first lane of PIE towards Changi, before Kim Keat Flyover within speed limit when the car in-front of me suddenly jammed his brake which led to my vehicle crashing into the back of his car even though I reacted in time and brake as the car rolled forward.
My car is car A, 2 passengers including me(driver)
The car I got into accident is car B, 2 passengers including the driver.
Before I manage to get off my car, there is already another 2 people from another car that is parked at road shoulder (I watched the video tape and found that they were already parked there even before the

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 06/12/2021 13:13
Officer In-Charge Of Case:	Classification Of Case:



accident happened). They came over and gave me a name card for their workshop. Which I felt was suspicious. I have the video tape, if is required by your side.

Didn't felt much pain during time of accident however, feet got swollen after few hours. Went to Urgent Care Centre at Kampung Admiralty and was given 10days MC due to fracture at ankle area. Car B's passenger is feeling alright as I have checked on them.

Subjects Involved			
Suspect			
Person Name	N.A		
Victim			
Person Name	ALOYSIUS TAY HUI MING	ID No	S9836719E
ID Type	NRIC NO	Age	23
Gender	Male	Language	English
Race	Chinese	Address	369 WOODLANDS AVENUE 1
Occupation	National Service Full Time		#09-861 SINGAPORE 730369
Mobile No	98314409	Is Informant A Victim?	Yes
Person Name	ALOYSIUS TAY HUI MING (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:
The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
06/12/2021 13:13

Classification Of Case:



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tay Ngak Mong
Period of Insurance : 06 Dec 2020 To 05 Dec 2021
Engine No. : 3A92UHK0272
Chassis No. : MMBSTA13AJH004307

Vehicle No. : SMG1536Z
Policy No. : 1800144741-01
Endorsement No. :
Issued Date : 24 Nov 2020

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Engine Capacity/Tonnage : 1,193.00 CC

Sum Insured : Market Value

First Year of Registration : 2018

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2018, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tay Ngak Mong - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2018 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623202

FULCOMIP2 - CT

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPLIC