(08/11/13)	wef
ASS. REC.	BY: Marcas

REF: CS/ASM 210/2367/4943 ASSIGNMENT | SUL 7647

From: Date: Estimated Cost: DD TP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: SLL 75676 at Workshop m/s KL/ Am- US-23	Veh No: SLL 136 / C Yr Regn: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Colour A/C: Insured / Std / NI / NA Colour T/Radio: Insured / Std / NI / NA	
Insured: SH 6 35000 Policy No. Claims No. S1M03NMK Sum Insured: Excess: (Client's Record) Make of Veh:	Eng/No: C/No: Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil / S/R/m / STD A/R/m or	
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Person Contacted:	Tyre Size: F: 79 PT PTR / SUMI / R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pura Fura Front Rear R/Bal. mm R/Bal. mm D.O.A. D.O.I. 7 / 12/2/ Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision.	
Date / Time Action / Instruction 09/12/21@5.24pm Informed Janice Koh, we are pending for estimate from repairer. Days Of Repair:		
Date/Time, File Pass tor	Resurvey No. of Trip: Survey Fee: Transportation:	