

(08/11/13)

we

ASS. REC. BY:

REF:

CS/MSG 21012386/RIGF3

3841

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 67614

at Workshop m/s YEW TEE AUTOMOBILE

of 39, WOODMANYS CLOSE #01-12 @ MTHA

Insured: MSIG

Policy No. _____

Claims No. 266250

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 56K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 67614 Yr Regn: 2017 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CERATO K3 1.6A c.c. 1591

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 71708 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNATX 411MH 5696778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm


D.O.A. 02/12/21 D.O.I. 08/12/21

Survey held at YEW TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
09/12/21 @ 5.05pm	revised to Christina Wong via Merimen.
02/06/22	email Christina Wong to seek mandate at final fig \$1867.76, 3 days.
02/06/22 @ 6.03pm	Christina informed proceed the mandate by email.
03/06/22 @ 9.57am	Informed Rasul, MSIG approved mandate at \$1867.76, 3 days.
	Rasul finalised LS \$1450, 3 days. (Red \$7868.96, 84%)

Date/Time, File Pass to?

1) 08/06 Typist

Date/Time, File Return to?

2)

Report Format: MER-TP

Lump Sum H.B. (\$ 1450)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

S + RS, SI

Photos

Others

TOTAL

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : MSIG INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5121974557	Date of Loss:	02/12/2021
Vehicle Reg. No.:	SLN6761G	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SLQ4011K
Any Injuries?	no	Contact No:	
Insured/Claimant:	WU ZHIHUI, ALLEN	Driver:	LING YUQI EUNICE

PARTS MODEL

Make/Model:	Kia, Cerato - KNAFE242	Vehicle Reg. Date:	15.05.2017
Vehicle Colour:	white	Engine Number:	G4FGGH667609
Chassis No:	KNAFX411MH5696778	Odometer:	-
Total Loss?	-	Est. Duration of Repair(Day)	10

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	6,718.96
Miscellaneous Items	340.00
Labour	1,210.00
Paintwork Labour	1,050.00
Towing	0.00
Gross Total(S\$):	9,318.96
GST 7.00%(S\$):	652.33
Nett Amount(S\$):	9,971.29

This claim is handled by: Tee Shu yi

REAR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>de/</i>	767.80	-20.00	614.24
2	1	REAR BUMPER LOWER SKIRT <i>de/</i>	260.50	-20.00	208.40
3	1	REAR BUMPER REFLECTOR RH <i>X</i>	121.50	-20.00	97.20
4	1	REAR BUMPER REFLECTOR LH <i>can/</i>	121.50	-20.00	97.20
5	1	REAR BUMPER SIDE RETAINER RH <i>X</i>	35.10	-20.00	28.08
6	1	REAR BUMPER SIDE RETAINER LH <i>na/</i>	35.10	-20.00	28.08
7	1	REAR BUMPER BRACKET RH <i>X</i>	81.50	-20.00	65.20
8	1	REAR BUMPER BRACKET LH <i>?</i>	81.50	-20.00	65.20
9	1	REAR BUMPER REINFORCEMENT <i>?</i>	315.70	-20.00	252.56
10	1	REAR BUMPER INNER SPONGE <i>?</i>	168.70	-20.00	134.96
11	1	REAR BUMPER REINFORCEMENT SMART KEY SENSOR <i>X</i>	153.20	-20.00	122.56
12	1	REAR BUMPER LOWER COVER RH <i>X</i>	124.80	-20.00	99.84
13	1	REAR BUMPER LOWER COVER LH <i>de/</i>	124.80	-20.00	99.84
14	1	REAR BOOT LID <i>X</i>	963.60	-20.00	770.88
15	1	REAR BOOT LID HINGE RH <i>X</i>	110.10	-20.00	88.08
16	1	REAR BOOT LID HINGE LH <i>X</i>	110.10	-20.00	88.08
17	1	REAR BOOT LID RUBBER <i>X</i>	132.80	-20.00	106.24
18	1	REAR BOOT LID LAMP RH <i>X</i>	711.20	-20.00	568.96
19	1	REAR BOOT LID LAMP LH <i>X</i>	711.20	-20.00	568.96
20	1	REAR BOOT LID LOCK <i>X</i>	111.50	-20.00	89.20
21	1	REAR END PANEL <i>?</i>	321.20	-20.00	256.96
22	1	REAR END PANEL INNER GARNISH <i>X</i>	104.80	-20.00	83.84
23	1	REAR END PANE KEYLESS SENSOR <i>X</i>	162.10	-20.00	129.68
24	1	REAR SPARE TYRE PANEL <i>X</i>	717.40	-20.00	573.92
25	1	REAR SPARE TYRE BOARD <i>X</i>	162.80	-20.00	130.24
26	1	REAR TAILLAMP RH <i>X</i>	844.10	-20.00	675.28
27	1	REAR TAILLAMP LH <i>?</i>	844.10	-20.00	675.28

Total Parts (S\$) 6,718.96

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>na/</i>	45.00	0.00	45.00 30
2	1	REAR SENSOR <i>scr/</i>	250.00	0.00	250.00 200
3	1	REAR END PANEL INNER GARNISH CLIPS <i>X</i>	45.00	0.00	45.00 <i>X</i>

Sub Total (S\$) 340.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 60 <i>X</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 60
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and	1,000.00	0.00	1,000.00 300

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.			

Gross Labour Cost (S\$) 1,210.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	0.00	50.00 X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	100.00	0.00	100.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	100.00	0.00	100.00 X
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00 200

Gross Labour Cost (S\$) 1,050.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
Hp 90010068

3 days

4/5

08/12/21 @ 1030

Resur after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/12/2021 11:44 (SGT)
Date of Accident	02/12/2021 07:53 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG SENGJA ROAD BEFORE SENJA WAY JUNCTION.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN6761G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	WU ZHIHUI, ALLEN
NRIC No	S8922384I
Email Address	Allen_wu_@hotmail.com
Mobile Phone No	(Phone) +65-98898227
Alternative Phone No	+65-98898227

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5121974557
Cover Note Number	-

DRIVER

Name of Driver	LING YUQI EUNICE
NRIC No	S9006235B

Date Of Birth	12/02/1990
Occupation	Indoor
Date Of Driving Pass	20/01/2011
Driving experience	10 YEARS AND 11 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97578787
Alt. Phone Number	-
Email Address	Allen_wu_@hotmail.com
Address	BLK 635A SENJA ROAD #19-243
Address complement	-
Postcode	671635
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	VIDEO FILE SIZE IS BIG. WILL PROVIDE TO INSURANCE WHEN REQUIRED.
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ4011K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	RICHARD
Contact Number	(Phone) +65-87529248

Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) 2

PASSENGER 1

Name UNKNOWN
Gender Female

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 2/12/2021 at about 7:53am, I was driving my car SLN6761G along Senja Road. As I was approaching the junction of Senja way, I slowed down and eventually came to a stop as I wanted to make a right turn into Senja way. I stopped because there was an oncoming vehicle. Shortly after I stopped, I felt my rear side of car was hit by something. I then realised that the car SLQ401K front side had hit the rear side of my car SLN6761G.

There were no injuries. That is all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 2/12/2021
21145hrs

Reporting Centre Personnel's Signature
Name: N. N. N.
NRIC/FIN No.: 993535

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	3841
Vehicle No.:	SLN6761G
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Dec 2021
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	G4FGGH667609
Chassis No.:	KNAFX411MH5696778
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$15,060.00
Original Registration Date:	15 May 2017
First Registration Date:	15 May 2017
Transfer Count:	1
Actual ARF Paid:	\$15,060.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2027
PARF Rebate Amount:	\$11,295.00
COE Expiry Date:	14 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$28,033.00
Total Rebate Amount:	\$39,328.00

The information contained herein is correct as at 08 Dec 2021

OK

Kia Cerato K3 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map



HUA YANG CREDIT PTE LTD



Price **\$55,800**

Depreciation  \$9,270 /yr
[View models with similar depre](#)

Reg Date 24-Apr-2017
(5yrs 4mths 15days COE left)

Mileage 96,000 km (20.7k /yr)

Manufactured  2017

Road Tax  \$738 /yr

Transmission Auto

Dereg Value  \$36,923 as of today ([change](#))

OMV  \$11,962

COE  \$52,000

ARF \$11,962

Engine Cap 1,591 cc

Power 95.3 kW (127 bhp)

Curb Weight 1,295 kg

No. of Owners 1