



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21012405/Ktf3n2	Date: 22/12/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJN 7702U	Veh. Inspected	SLN 5543B
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10012817/EE	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	08/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ (A)	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KMHC851CVHU035133	Colour	METALLIC GREY
	Odometer	316058 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	GOODYEAR	8 mm
	L/H Front Tyre	225/45 R17	GOODYEAR	8 mm
	R/H Rear Tyre	225/45 R17	GOODYEAR	8 mm
	L/H Rear Tyre	225/45 R17	GOODYEAR	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/12/2021	Inspection Date	08/12/2021
	Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	