

MEUC (Ysum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 06.12.2021  
Time: 11:39:44  
Page: 1  
Jumani

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305496870  
REGN NO : SHA2358E ✓  
MILEAGE : 000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 28.09.2018  
DATE/TIME IN : 06.12.2021 10.05  
ACCIDENT DATE : 06.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	/cut
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/scr
0003	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	? Xsic
0004	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/pic
0005	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	10.00	122.13	/cut
0006	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40	? Xsuc
0007	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	Xsuc
0008	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	/scr

SUB-TOTAL : 1,422.69 ✓

JOB NATURE

0000	PB	PANEL BEATING	400.00	360 X 350
0001	SP	SPRAYPAINT CHARGE	300.00	250
0002	L	REMOVE/REFIX REVERSE SENSOR	50.00	20 ✓

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 06.12.2021

Time: 11:39:44

Page: 2

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305496870  
 REGN NO : SHIA2358E  
 MILEAGE : 000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 28.09.2018  
 DATE/TIME IN : 06.12.2021 10:0  
 ACCIDENT DATE : 06.12.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0003 20-05 RENEW ADVERTISMENT STICKER-FENDR				200.00	N/C	
0004 17-01 CHECK ALL LIGHTING				50.00	20	
SUB-TOTAL :						1,000.00
TOTAL :						2,422.69

AUTHORISED : YES / NO

MVA NAME &amp; SIGNATURE

SURVEYOR NAME &amp; SIGNATURE

DATE :

DATE :

Thron@Lkh auto-lom

82235769

6/12/21 11:530

L/S after repair photo

2 day swp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: