Date :		305497151 09/12/21	_	Comf	ONTERING OrtDelGro Engineering Pte Ltd					
FIN.	ALIZAT	TION F	ORM	Line			yang Drive Singapore 508969 3546 8156			
Attn	· -			LKK		Fax	:			
				THEVAN						
Vehicle Reg No. : SHC			: <u>SHC</u>	C7647C		Date of Accident	07/12/21			
The	survey	and e	stimates of	the repairs of the a	above-mentions	ud vobialo asa as	follows:-			
1.			ob shall bi		NTUC		SLF 762K			
2.	The	finalize	ed amount	shall be:						
	(a)	Spar	e Parts aft	er List discount						
	(b)			etc if any)						
		(b) Labour Charges (include advertisement stickers etc,if any) Total for Part-By-Part Repair Cost								
	(c.)	Lump	sum Repa	air (if applicable)			£4 000 00			
		Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost			r Less: 20%		\$1,900.00 \$1,900.00			
	Withi	n 7 wo	rking days	5	rrect and Conf	rmed if there is	s no reply from you			
4 .	Withi	n 7 wo	eat the abourking days	5	V	irmed if there is We confirm the enalized amount	estimates and			
	Withi	n 7 wo k you f	rking days	5	V fi	Ve confirm the e	estimates and			
	Than	n 7 wo	rking days	5	v fi S	Ve confirm the e	estimates and			
	Than	n 7 wo	rking days	sistance.	V fi S N	Ve confirm the enalized amount	estimates and THEVAN			
	Than Signa	n 7 wo	or your ass	sistance.	V fi S N	Ve confirm the enalized amount ignature:	estimates and			
5.	Thani Signa Name Tel Fax	n 7 wo	LIM T S 6214839	sistance.	V fi S N	Ve confirm the enalized amount ignature:	estimates and THEVAN			
5.	Thani Signa Name	n 7 wo	LIM T S 6214839	sistance.	V fi S N D	Ve confirm the enalized amount ignature:	estimates and THEVAN			
5.	Signa Name Tel Fax	n 7 wo	LIM T S 6214839	sistance.	V fi S N	Ve confirm the enalized amount ignature:	estimates and THEVAN			
5.	Signa Name Tel Fax	ture::::::::::::::::::::::::::::::::::::	LIM T S 6214839 6546815	sistance. UWA 88 66	V fi	Ve confirm the enalized amount ignature :ame :ate :	estimates and THEVAN			
5. For O	Signa Name Tel Fax Official ental Ra ss of In	ture: : : : : Use O	LIM T S 6214839 6546815	sistance. UWA 88 66	V fi	Ve confirm the enalized amount ignature :ame :ate :	estimates and THEVAN			
For O	Signa Name Tel Fax Official ental Ra ss of In	ture: : : : : : : : : : : : : : : : : : :	LIM T S 6214839 6546815	sistance.	V fi	Ve confirm the enalized amount ignature :ame :ate :	estimates and THEVAN			
. Re	Signa Name Tel Fax Official ental Ra ss of In	ture: : : : : : : : : : : : : : : : : : :	LIM T S 6214839 6546815	sistance. UWA 88 66	V fi	Ve confirm the enalized amount ignature :ame :ate :	estimates and THEVAN			
. Re	Signa Name Tel Fax Official ental Ra ss of In	ture: : : : : : : : : : : : : : : : : : :	LIM T S 6214839 6546815 nly Paid	sistance.	V fi	Ve confirm the enalized amount ignature :ame :ate :	estimates and THEVAN			

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK-

DATE:

MODEL:

7-Dec-21

Hyundai loniq

VEHICLE NO .: SHC7647C

INSURANCE: NTUC (以5)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Front Door RH	1		\$1,797.20	<r></r>
	Rear Door RH	1		\$1,789.90	DT
	Rear Door Upper Hinge RH	1		\$173.90	
	Rear Door Lower Hinge RH	1		\$170.50	× SUC /
	SUB TOTAL LESS 20%			\$3,931.50 \$786.30	/
	DISCOUNTED TOTAL			\$3,145.20	
	Frt Door ComfortDelGro RH Rear Door APPS RH	1		\$75.00, \$80.00,	nee / nee
	NETT SUB			\$155.00 \$15.50	
	LESS 10% NETT TOTAL			\$139.50	
	TOTAL SPARE PARTS			\$3,284.70	
	Labour Charge Panel Beating			\$800.00	360 X350
	Spray Painting			\$600.00	500
	Tuff Kote			\$40.00	20/
	TOTAL LABOUR		-	\$1,440.00	V
	ESTIMATE TOTAL			\$4,724.70	
				- 14.00	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

> Thevan Clkhauto. low 82235769 7/12/2/ 1636 L/5 after (par photo 2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: