

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/12/2021 15:06 (SGT)
Date of Accident 07/12/2021 13:45 (SGT)
Exact Location of Accident Near 141 Tanglin Rd, Singapore 247929
Additional Location Information TANGLIN ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMB3516U

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TOWER TRANSIT SINGAPORE PTE LTD
Company Reg No 2XXXXX417K
Email Address feedback@towertransit.sg
Mobile Phone No (Phone) +65-18002480950
Alternative Phone No (Office) +65-18002480950

VEHICLE PARTICULARS

Manufacturer Alexander Dennis
Model ENVIRO500
Variant DOUBLE DECK
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Bus
Transmission Auto
CC 12000

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number D-19094584MFBP
Cover Note Number -

DRIVER

Name of Driver TAN KEOW SING
NRIC No SXXXX165B

Date Of Birth	20/04/1968
Occupation	Outdoor
Date Of Driving Pass	07/08/2008
Driving experience	13 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-18002480950
Alt. Phone Number	-
Email Address	feedback@towertransit.sg
Address	C/O : 21 BULIM DRIVE
Address complement	BULIM BUS DEPOT
Postcode	648170
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

please refer attached

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK3899Y
Vehicle Manufacturer	Mitsubishi
Vehicle Model	Fuso
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	MOO KEN SENG
NRIC No	SXXXX745B
Contact Number	-
Address	-

Address complement -
Postcode -
Insurance Company Name ERGO Insurance Pte. Ltd.
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

TAN KEOW SING 10604
[Signature]
 TUE 07/12/21

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

6BK 3899T Richard Mille

SMB 3516U

Tanjong Pagar



Statement Form

BC Name: TAN KEOW SING Date Taken: TUE. 07/12/21
 BC No : 10604 Time Taken: 16:45 H.
 Nature of Incident: Driver of 6BK 3899 Y Reverse Suddenly From (x) Mt ^{SMB}
 Date of Incident: TUE. 07/12/21 Time of Incident: 13:40 H. _U 3516
 Service No: 106 Bus Reg No: SMB 3516 U Duty No: 106 AV5

Details:

While travelling along Orchard Rd. Approaching Tanglin Place, Veh. 6BK 3899 Y which was in front me, making left turn onto a path at the building seems as "Richard Mills"; a big advertisement. Of course, I kept a distance away from it and make sure the veh. has totally turned on! Then, I moved my bus slowly.

Suddenly; I heard a loud noise and 2 passengers standing at the rear door were shaken by the 6BK 3899 Y which had suddenly reversed out to the main road from the path as mentioned above, and bang onto the rear door of the bus I was driving, i.e., SMB 3516 U, and it was badly damaged. Police officers, and later on cc. staff; Traffic police officer were then to assist and helped.

*I confirmed that the above statement given by me is correct to the best of my knowledge.

TAN KEOW SING
10604 [Signature] Tue. 07/12/21
 BC Name & No. Signature Date & Time

Statement Taken By:

Peter Lim 15
 Name Designation











