

## ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No:

at Workshop m/s PREMIUM AUTO

of

Insured:

Policy No.

Claims No. 5221720747SG

Sum Insured: Excess: 0/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|                                     |     |
|-------------------------------------|-----|
| N/S                                 | O/S |
| <input checked="" type="checkbox"/> |     |

Bal. or Market Value: \$178k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMS7456T Yr Regn: 12 Mar 2020

Type ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: AUDI A4 c.c. 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 24470 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZF47KA117936 \*

Gen. Cond ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 09-12-2021

Survey held at W/S 2:30PM

Des. of Damages: Frt / ☒ Rea / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/12/21@3.36pm revert to AIG via Merimen.

10/12/21@3.50pm Kok Chong informed C/A via Merimen.

☒ Yes / ☐ No BI Involved

10/21/21@5.23pm Informed Zoey C/A &amp; ex:\$0/- by email.

GQ finalised with Jia Yee final fig \$4635.12, 3 days. (Red \$6124.88, 57%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : A/Weekend (\$

3 + RS. SI

Photos

Other:

TOTAL

Report Finalised

MER-OD

Long Term / MPB / 4635.12