



Claim	<a href="#">S1M03NZ8</a>
Reference	CS3/ASM21012516/Gvy3e2 
Loss Date	9 December 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	10 Dec 2021 8:54:33 AM
Request Date	13 December 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve  
invoice

Add Invoice

Vehicle Information

Incident	SLG6770S
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Camry


Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Additional Instructions

Messages2	Invoices	History	Documents	Assessment	Metrics	Notes
Add						
REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC2108696	Final Invoice	\$107.00	20/12/21 4:54 PM	Waiting for Approval		<div></div>

Totals

Outstanding Invoices	\$107.00	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		
Total	\$107.00		