



Claim	S1M03NZ8
Reference	CS3/ASM21012516/Gvy3e2 
Loss Date	9 December 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	10 Dec 2021 8:54:33 AM
Request Date	13 December 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SLG6770S
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Camry

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2108696.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2021

FAQ English (SG) ▾ Elaine Kuan ▾			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	...	s / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 December 2021
	 LKKPhotosIn4_compressed.pdf.pdf	Evidence	Photos		LKK AUTO CONSULTANTS PTE LTD (TP)	14 December 2021
	 EMAIL FROM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others		NIKAM Santosh Pandurang	10 December 2021
	 SLG6770S TP GIA.pdf.pdf	Reports & Statement	GIA Report		NIKAM Santosh Pandurang	10 December 2021