

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21003812	Page	1
Registration No	: SLR8925S	Date	: 10. Dec 2021		
Chassis No	: JHMRC1880HC203488	Customer No.	: WZL009		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: TAN TAI MENG	Engine No	: K24W72041132		
Ins Policy No.	:	Date Time	: 10. Dec 2021 11:47:11 AM		
Date of Accident	: 10/12/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN TAI MENG OWNER INSURER: LIBERTY INSURANCE ACC DATE: 10/12/2021 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE TP VEH: GBC2818E						
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD	1	1078.20	25	808.65	56.61	865.26
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.02	30.82
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.00	25	13.50	0.95	14.45
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.00	25	13.50	0.95	14.45
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	0.88	13.48
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.20	3.12
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	0.96	14.61
76711-T6A-003	CAPPVOT	1	5.20	25	3.90	0.27	4.17
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1141.90	25	856.42	59.95	916.37
34155-T6A-003	LIGHT ASSYL.LID	1	411.80	25	308.85	21.62	330.47
34150-T6A-003	LIGHT ASSY,R.LID	1	411.80	25	308.85	21.62	330.47
33500-T6A-003	TAILLIGHT ASSYR.	1	893.80	25	670.35	46.92	717.27
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.20	25	93.90	6.57	100.47
74800-TF0-J02	LOCKTAILGATE	1	197.70	25	148.27	10.38	158.65
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	245.70	25	184.27	12.90	197.17
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	187.20	25	140.40	9.83	150.23
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	220.00	25	165.00	11.55	176.55
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	11.50	25	8.62	0.60	9.22

Printed on 10/12/2021 1:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555

Registration No : SLR8925S

Chassis No : JHMRC1880HC203488

Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)

Owner's Name : TAN TAI MENG

Ins Policy No. :

Date of Accident : 10/12/2021

Document No. : SQT21003812 Page 2

Date : 10. Dec 2021

Customer No. : WZL009

Svc Advisor : RUEBEN THOMAS

Engine No : K24W72041132

Date | Time : 10. Dec 2021 11:47:11 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
75701-T6A-000	EMBLEMH	1	28.10	25	21.07	1.47	22.54
04715-T6A-000ZZ	FACERR.BUMPER	1	573.20	25	429.90	30.09	459.99
91505-TM8-003	CLIP,BUMPER	9	2.30	25	15.52	1.09	16.61
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	48.40	25	36.30	2.54	38.84
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37
71502-T6A-003ZG	FACER.RR.BUMPER GARNISH	1	81.90	25	61.42	4.30	65.72
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	110.50	25	82.87	5.80	88.67
84665-T6A-J12ZA	LINING COMPL.RR.SIDE	1	670.30	25	502.72	35.19	537.91
84615-T6A-N22ZD	LINING COMP,R.RR.SIDE	1	782.70	25	587.02	41.09	628.11
74940-TR0-003	BUZZER ASSYSMART	1	64.10	25	48.07	3.36	51.43
38387-SLE-003	ANTENNA ASSY,L.RR.	1	64.60	25	48.45	3.39	51.84
76700-T6A-J01	WIPER MOTOR ASSY	1	256.40	25	192.30	13.46	205.76
76720-T4N-H01	ARM,RR.WIPER	1	45.40	25	34.05	2.38	36.43
76730-S3N-003	BLADEWINDSHIELD WIPER	1	45.70	25	34.27	2.40	36.67
66100-T6A-Q01ZZ	PANEL COMP,REAR	1	491.40	25	368.55	25.80	394.35
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	360.30	25	270.22	18.92	289.14
72841-SH3-315	OILSHEET	1	43.40	25	32.55	2.28	34.83
Sum Item					6958.33	487.08	7,445.41
BO-VK-ASTRO-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT.	1	200.00		200.00	14.00	214.00

Printed on 10/12/2021 1:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21003812	Page	3
Registration No	: SLR8925S	Date	: 10. Dec 2021		
Chassis No	: JHMRC1880HC203488	Customer No.	: WZL009		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: TAN TAI MENG	Engine No	: K24W72041132		
Ins Policy No.	:	Date Time	: 10. Dec 2021 11:47:11 AM		
Date of Accident	: 10/12/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG01S	TO VACUUM & CLEAR SHATTERED GLASS	1	350.00		350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00		650.00	45.50	695.50
BMU30R	REMOVE & INSTALL EXHAUST SYSTEM.(N)	1	450.00		450.00	31.50	481.50
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	6200.00		6200.00	434.00	6634.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3300.00		3300.00	231.00	3531.00
Sum Labor					14580.00	1,020.60	15,600.60

Survey By

Date & Time

Excess

Status

Signature

Total Amount 21,838.33 1,528.68 23,367.01

Total (Inclusive of GST) 23,367.01

Printed on 10/12/2021 1:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/12/2021 12:27 (SGT)
Date of Accident	10/12/2021 10:55 (SGT)
Exact Location of Accident	Near 1 Aljunied Walk, Singapore 387293
Additional Location Information	PIE TOWARDS CHANGI (L/POST 552F)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8925S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN TAI MENG
NRIC No	SXXXX851B
Email Address	simjunxiong@gmail.com
Mobile Phone No	(Phone) +65-98423157
Alternative Phone No	(Home) +65-98423157

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2400

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SD20V08517
Cover Note Number	-

DRIVER

Name of Driver	SIM JUN XIONG
NRIC No	SXXXX084I

Date Of Birth	27/05/1991
Occupation	Indoor
Date Of Driving Pass	11/03/2011
Driving experience	10 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90496643
Alt. Phone Number	-
Email Address	simjunxiong@gmail.com
Address	BLK 609 BEDOK RESERVOIR ROAD
Address complement	#10-646
Postcode	470609
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Relative
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	FBC8560H
Insurance Company of Other Vehicle Owned by Driver	FWD Singapore Pte. Ltd.

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2818E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	TAN ENG HOCK
NRIC No	SXXXX546E
Contact Number	(Phone) +65-98575806
Address	-

Address complement	
Postcode	
Insurance Company Name	Lonpac Insurance Bhd
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

Vehicle
Number: SLR 8925 S

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature (If driver is not the policyholder)
Date & Time: 10/12/2010 @ 1140 am

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

(70 km/h) (bump) (bump) (bump)
 2000, 2000 5500

Vehicle Number: SIR 29255

SKETCH PLAN



A → SIR 29255
 B → 63C2818E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10 Dec 2021 at about 10:55hrs, while I was driving
 vehicle SIR 29255 and was stationary due to being in the
 queue. I felt an impact from the rear and I looked at the
 rear mirror and noticed an vehicle bump and collided into
 the rear of the vehicle I was driving. I noticed an impact
 with the driver's side window, which seemed to be injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature (If driver is not the policyholder)
 Date & Time: 10/12/2021 @ 11:42 am

Reporting Centre Person's Signature
 Name:
 NUC/INN No: