

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

China-CL (sum)

Date: 09.12.2021

Time: 13:55:23

Page: 1

Juman

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305497432
REGN NO : SH 7740J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.10.2016
DATE/TIME IN : 09.12.2021 12:15
ACCIDENT DATE : 08.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	DT
0002	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0003	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	Cut
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	N/C
0006	04-01-0103-0851-G	REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	DIS CRA check consistency?
0007	04-01-0103-0577-G	PANEL ASSY-TRUNK LID#	1	2,609.80	20.00	2,087.84	DT
0008	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	2.00	135.70	Cut
0009	04-01-0103-0907-G	BRKT ASSY-RR BUMPER SIDE	1	35.80	20.00	28.64	Koum?
0010	04-01-0103-0742-G	STAY-RR BUMPER LH	1	160.60	20.00	128.48	?
0011	04-01-0103-0787-G	EMBLEM-I40	1	67.90	20.00	54.32	N/C
0012	04-01-0103-0786-G	EMBLEM-CRDI	1	52.40	20.00	41.92	N/C
0013	04-01-0103-0800-G	SYMBOL MARK-TRUNK LID	1	63.10	20.00	50.48	N/C

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305497432
 REGN NO : SH 7740J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.10.2016
 DATE/TIME IN : 09.12.2021 12:1
 ACCIDENT DATE : 08.12.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 28-01-0103-0006-A REAR BOOT TEL NUMBER CTPL	1	N	30.00	2.00	30.00
0015 28-01-0103-0005-A REAR BOOT LOGO CTPL	1	N	30.00	0.20	30.00
SUB-TOTAL					: 3,693.70

JOB NATURE

0000 PB	PANEL BEATING	600.00	560
0001 SP	SPRAYPAINT CHARGE	600.00	506
0002 17-01	CHECK ALL LIGHTING	50.00	20
0003 L	REMOVE/REFIX REVERSE SENSOR	50.00	20
0004 20-05	ADVERTISMENT STICKER-BUMPER	100.00	/
0005 20-05	ADVERTISMENT STICKER-FENDER	200.00	/
0006 20-05	ADVERTISMENT STICKER-BOOTLID	100.00	/
SUB-TOTAL		: 1,700.00	

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305497432
REGN NO : SH 7740J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.10.2016
DATE/TIME IN : 09.12.2021 12:1
ACCIDENT DATE : 08.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,393.70

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Thuan@LKKauto.com
82235769
9 8/12/21 1600
45 after repair photo
3 day sup

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 09.12.2021 13:37

Page : 1

n: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4150167

JC NO305497432

VER

COMFORT TRANSPORTATION PTE LTD

7010045

VER NO.

SS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

3) 65508755

(O)

2)

INT CARD NO.

REGN NO:

SH 7740J

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN
09.12.2021 12:15

YR OF MANU.

13.10.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU093754

COMPLETION DATE/TIME:

JOB DESCRIPTION


Ident Date: 08.12.2021

DURE: 3P.08.12.2021

JO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 7740J

JU CHINA

Vehicle No.:

SH 7740J

Service Advisor

Signature/Date

Name of Service Advisor

Date

ned to Service Reception upon collection

To be kept by Security Guard