



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21012543/Evf3n2 Date: 27/12/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 702D		Veh. Inspected	SJY 9028L
Policy No.			Coverage (\$)	0.00
Claim No.	C10012837/KY		Excess (\$)	0.00
Assign From	IVY RATILLA		Assign Date	13/12/2021
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO		c.c	1591
Engine No.	HIDDEN		Year of Reg.	2010
Chassis No.	KNAFU411LA5171110		Colour	BLUE
Odometer	240944 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	5 mm
	L/H Front Tyre	195/65 R15	MICHELIN	5 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	5 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	06/12/2021	Inspection Date	14/12/2021
	Survey held at	WIN AUTOMOTIVE SERVICES BLK 6, 399J WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 678008		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	