ASS. REC. BY: Kenneth

REF: AXA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1.B.I % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJTB 7882U Yr Regn: 12.12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Chevrolet Epica c.c 1991

Colour White / Red A/C: Insured / Std / NI / NA

Sp.Reading 38809 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL1LA69RJBB 108448

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : NIL / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Falken

Front		Rear	
R/Bal.	8 mm	R/Bal.	7 mm
L/Bal.	8 mm	L/Bal.	7 mm
D.O.A.	31/1/16	D.O.I.	29/2/16

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S 1/4

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1/3	@ 2001 Send
"	File pass to Catherine

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Survey Fee: _____

Transportation: ___S + RS___SI

Photos _____

Others _____