

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7882U - AXA

Not Authorized
Hong @ 2006

Candy

Vehicle No.:	SHB 7882U - Candy
Chassis No.:	KL1LA69RJBB108448
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	31.01.16
Third Party Insurer :	AXA

PART		LIST	
1	1 Front Bumper	\$	<i>N</i> 1,202.00 X
2	1 Front Bumper Retainer RH	\$	<i>Sn</i> 102.00 X
3	1 Bumper Fog Lamp Cover RH	\$	<i>Sn</i> 32.40 X
4	1 Front Fender RH	\$	<i>N</i> 837.60 X
5	1 Front Fender Liner RH	\$	<i>Sn</i> 47.00 X
6	1 Headlamp RH	\$	<i>Sn</i> 816.00 X
7	1 Windscreen Washer Tank	\$	<i>Sn</i> 62.00 X
8	1 Windscreen Washer Tank Motor	\$	<i>Sn</i> 51.00 X

TOTAL	\$	3,150.00
10%	\$	315.00
	\$	2,835.00

Special Nett

1	1 Set Front Bumper Fastener Clip	\$	<i>nn</i> 24.00 X
2	1 Set Front licence plate with holder	\$	<i>Sn</i> 192.00 X
3	1 Set Front Fender Liner clip RH	\$	<i>nn</i> 30.00 X
4	1 Front Wheel Rim Hub Cap RH	\$	<i>Sn</i> 166.30 X
5	1 Front Tyre RH	\$	<i>Sn</i> 180.00 X
6	1 Front Tyre Rim RH	\$	<i>Sn</i> 126.00 X

TOTAL	\$	718.30
TOTAL PARTS	\$	3,553.30

To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>nn</i> 1,400.00 X
Putty and spray painting of the affected portion.	\$	1,350.00 <i>2006</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7882U - AXA

Candy

To rust-proofing of the affected areas.

\$

un 170.00 X

TOTAL	\$	3,480.00
Over All Total	\$	7,033.30

Repair Days

5 Days

1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: