

CYCLE & CARRIAGE

AG-OD CLAIM
SURVEY: 15/12/21
UKL - STEVE

VEHICLE NO : SJG5115P

MODEL : KIA/CERATO 1.6 A GT LINE

WIP : 43866

Material	:	\$	<u>1,860.80</u>
Labour	:	\$	<u>1,050.00</u>
Sub-Total	:	\$	<u>2,910.80</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>2,610.80</u>
GST 7%	:	\$	<u>182.76</u>
Grand Total	:	\$	<u>2,793.56</u>
Finalise By/Date	:	<u>Umy on 21/12/21</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS + 2 days (wk end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE


GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 15/12/2021	Cust No/Name	LCV05366/GOH KIAN AIK
	Reg No/Reg Date	SJG5115P / 21/01/2021
	Date In/Mileage	20/12/2021/ 26217
	Chassis/Package	KNAF5416MM5100877 /#
	Engine No	G4FGLH711842
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/12/2021/ 16:06	BLE	884 / Lauro Songcuan	43866			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								400.00 ✓
RENEW FRONT BUMPER								
E PNT98000								350.00 ✓
SPRAY PAINT FRONT BUMPER								
A 54900099								30.00 ✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
E PNT88000								80.00 ✓
REMOVE & REFIT FRONT PARKING ASSIST SENSOR								
M SUNDRY								20.00 ✓
SUNDRIES								
S SPECIALISTJOB								50.00 ✓
SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)								
X EXC								-300.00
EXCESS								
X COVER-FR BUMPER ✓					1.00	633.00	20.00	506.40 ✓
X GRILLE-FRONT BUMPER ?					1.00	485.00	20.00	388.00 ?
X GRILLE ASSY-RADIATOR ✓					1.00	328.00	20.00	262.40 ✓
X MOULDING-FRONT BUMPER, LH ?					1.00	216.00	20.00	172.80 ?
X ULTRASONIC SENSOR ASSY-P.A.S ?					2.00	163.00	20.00	260.80 ?
X ORNAMENT-KIA NO.115 ✓					1.00	32.00	20.00	25.60 ✓
X COVER-FR BUMPER FOG LAMP, LH					1.00	15.00	20.00	12.00 X
X WIRING ASSY-BUMPER EXTENSION					1.00	207.00	20.00	165.60 X
X ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	67.20 X
Z TEXT								
AIG - OD CLAIM								
SURVEY: STEVE (LKK) 15/12/2021								
DOA: 10/12/2021								
03 DAYS								
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>								

Parts	1,860.80	Nett	2,610.80
Labour	980.00	7% GST on	182.76
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	2,793.56
Sundry/Others	-280.00		
Total(w/o GST)	2,610.80		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SJG 5115 P

	<u>Materials</u>	<u>Cost \$</u>
1	Cover- FR Bumper Fog Lamp, LH	15.00 - BR
2	Wiring Assy- Bumper Extension	207.00 - BR
3	Absorber- Front Bumper Energy	84.00 - BR
		<hr/>
		306.00
	20% Discount	61.20
		<hr/>
		244.80
	7% GST	17.14
	Total	<hr/> <hr/> 261.94

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: STG 5115P

WIP: 43866

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Grille Front Bumper	? / SUPP		- RR	
2	Moulding Front Bumper LH	? / SUPP	(check)	- RR	
3	Ultrasonic Sensor Assy P.A.S X2	? / SUPP		- RR	
4	Wiring Harness Front Bumper	? / SUPP		- RR	Steve
5	Absorber Front Bumper Energy	? / SUPP		- RR	16/12/21
6	Cover Fog Lamp Front LH	? / SUPP		- RR	
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			



	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATO

SURVEYOR: STEVE

 **Fault Code Searching**

Rescan Erase All DTC Go to DTC Save



12/12


System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0261	VCI Ver.	02.63
ECU Ver.	M-E-K-01-00-0200	OS Ver.	Android 10

 **Fault Code Searching**

Rescan Erase All DTC Go to DTC Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0261	VCI Ver.	02.63
ECU Ver.	M-E-K-01-00-0200	OS Ver.	Android 10

 **Fault Code Searching**

Rescan Erase All DTC Go to DTC Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0261	VCI Ver.	02.63
ECU Ver.	M-E-K-01-00-0200	OS Ver.	Android 10