

1.

2.

AXA INSURANCE PTE LTD

SINGAPORE 068811 ATTN: NG STACEY

Insured Veh.

Assign From

Make & Model

Engine No.

Chassis No.

Odometer

Policy No.

Claim No.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT CS3/ASM21012558/Bty3e2 Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 29/12/2021 Code: ASM Policy Particulars :- (THIRD PARTY CLAIM) **FBR 233D** SHD 9978D Veh. Inspected Coverage (\$) 0.00 S1M03NWC Excess (\$) 0.00 NG STACEY **Assign Date** 13/12/2021 **Vehicle Particulars & Condition** HONDA ADV150 ABS CVT 149 C.C 2020 Year of Reg. MH1KF6118KK007846 RED Colour Steering **IN ORDER**

IN ORDER SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 110/80/14 MAXXIS 6 mm L/H Front Tyre mm 130/70/13 **MAXXIS** R/H Rear Tyre 6 mm L/H Rear Tyre mm

4. **Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

HIDDEN

Page No.:1 of 1

5. **General Information** 20/11/2021 13/12/2021 (02:53 PM) Inspect Date / Time Accident Date MS CAR AUTO PTE LTD Survey held at 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/ASM21012558/Bty3e2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser