



Claim	S1M03NMP
Reference	CS3/ASM21012560/Vty3e2 
Loss Date	30 November 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	7 Dec 2021 9:21:30 AM
Request Date	13 December 2021
Due Date	
Services	Standard workshop survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SNA6523Y
Vehicle	
Registration #	
Make	TPVD TOYOTA
Model	ALPHARD

Service Address

, , ,

Primary Contact/Insured

CINDY LIM SOK SYN (CINDY LIM SHUXIN) MRS
CINDY CHESNEY
BLK 88 CAIRNHILL ROAD, 229688, Singapore
81118870

Claim Handler

ONG Kian Theng Derick

derick.ongkt@axa.com.sg

Additional Instructions TP WS :Lim
Motor Pte Ltd

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2200299.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	14 January 2022

FAQ English (SG) ▼ Elaine Kuan ▼			E	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	14 January 2022
	 Resurvey Photo-1.pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	14 January 2022
	 AXA Immediate Advice _ TP - SNA 6523Y.pdf.pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 January 2022
	 LKKPhotosIn6.pdf.pdf		Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	11 January 2022
	 S1M03NMP_Final inspection photographs.pdf.pdf		Evidence	Photos	ONG Kian Theng Derick	20 December 2021
	 Survey Photos.pdf.pdf		Evidence	Photos	SHAWN CHUA (AXA)	10 December 2021
	 EMAIL FROM WS.pdf.pdf		Letters and Correspondence	Others	NIKAM Santosh Pandurang	7 December 2021

	FAQ	English (SG) ▼	Elaine Kuan ▼	E	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...		Reports & Statement	GIA Report	NIKAM Santosh Pandurang	7 December 2021