


ASS REC. BY: Tolum REF: CC4/A142102565/Bea3 Asher

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 14/12/2021  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SJP 991L  
 at Workshop m/s Accident Assist SG  
 of 24 Sin Ming Lane # 0194  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJP 991L Yr Regn: 11/3/2009  
 Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Airwave 1.5 c.c. 1496  
 Colour: Silver NC: Insured / Std / NI / NA  
 Sp. Reading: 200681 T/Radio: Insured / Std / NI / NA  
 Eng/No: L15A5207717  
 C/No: 4J11306347  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brako:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/60/15 Dayton  
 R: 185/60/15 Goodrich

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 7000/-  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS WP  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

Front		Rear	
R/Bal.	<u>3</u> mm	R/Bal.	<u>3</u> mm
L/Bal.	<u>3</u> mm	L/Bal.	<u>3</u> mm

 D.O.A. 7/12/2021 D.O.I. 14/12/2021  
 Survey held at Accident Assist SG  
 Des. of Damages: Frt /  Rear /  O/S /  N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: <u>3000/- - 4,000/-</u>
	Recommended COR: <u>NV \$2,200.00</u> COR of LS \$3650/- being higher than NV.
	NV <u>7000/-</u> PV <u>4770/-</u> <u>NV 2221/-</u>

Tolum  
8/4/2022

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ 1)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

Report Format: \_\_\_\_\_  
 Lump Sum / I.S.I. / \_\_\_\_\_

# Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970  
 Tel: 6334 1182 Email: management@assist.com

Registration no. : SJP991L / Honda Airwave 1.5M A  
 Date : 14-Dec-21 Estimate No. : AAS008\_SJP991L\_AIRWAVE

S/N	Qty	Item	Amount
-----	-----	------	--------

## LIST ITEMS

S/N	Qty	Item	Amount	Remarks
1	1	Rear bumper	956.00	✓ CUTV
2	1	Rear bumper side retainer <del>o/s</del> N/S	62.40	91.00 NECV
3	1	Taillamp <del>o/s</del> N/S	335.00	530.00 CUTV
4	1	Rear side body panel <del>o/s</del> NS Fender	1125.00	1250.00 DDV
5	1	Rear side body inner panel o/s		1305.30 NDX
6	1	Rear side body panel glass moulding o/s		135.00 NDX
7	1	Rear side body panel emblem (Airwave) o/s		85.30 NNX
8	1	Rear side body panel inner trim o/s		344.90 } NDX
9	1	Rear side body panel inner shield o/s		163.50 }
10	1	Rear door <del>o/s</del> NS	987.00	1161.30 DDV
11	1	Rear door weather strip o/s		115.80 }
12	1	Rear door inner lock o/s		290.00 }
13	2	Rear door hinge @ SGD 48.40		96.80 }
14	1	Rear door checker o/s		65.00 } NDX
15	2	Rear door outer handle o/s		130.30 }
16	1	Rear door inner trim o/s		451.60 }
17	1	Rear door inner seal o/s		75.00 }
18	1	Rear door glass regulator assy o/s		471.80 }
19	1	Rear door glass run channel o/s		103.65 }
20	1	Rear door black tape <del>o/s</del> NS	32.20	60.00 NECV
21	1	Rear axle		1406.80
22	1	Rear wheel hub o/s		364.00
23	1	Rear wheel hub bearing o/s		122.00
			3497.60	9775.05
Less 20%			699.52	1955.01
			2798.08	7820.04

## SPECIAL NETT ITEMS

1	1	Sundries		80.00 NNX
2	1set	Rear bumper clips		✓ 30.00 NECV
3	1set	Taillamp clips <del>o/s</del> NS		✓ 25.00 NECV
4	1	Taillamp seal <del>o/s</del> NS	20.00	30.00 NECV
5	1	Rear side body panel sealant <del>o/s</del> NS Fender	30.00	100.00 NECV
6	1	Rear side body inner panel o/s		100.00 }
7	1set	Rear side body panel inner trim clips o/s		80.00 } NNX
8	1set	Rear side body panel inner shield clips o/s		60.00 }
9	1	Rear door sealant	30.00	70.00 NECV

# Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970

Tel: 6334 1182 Email: management@assist.com

Registration no. : SJP991L / Honda Airwave 1.5M A  
 Date : 14-Dec-21 Estimate No. : AAS008\_SJP991L\_AIRWAVE

S/N	Qty	Item	Amount
10	1	Rear door inner trim clips o/s	80.00 <del>NNX</del>
11	1	Rear alloy rim R15 o/s	480.00 <del>NDX</del>
12	1	Rear tyre R15 o/s	220.00 <del>NDX</del>
13	1	Brake fluid	75.00 <del>NNX</del>
			135.00 1430.00
<b>PART TOTAL</b>			<b>9250.04</b>

### LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	-1500.00 } 1600.00
2	1	To remove/replace damaged parts & components.	800.00
3	1	To apply undercoating for rust roofing.	100.00 <del>NNX</del>
4	1	Check wiring system after disconnect and connect.	100.00 30.00 ✓
5	1	To conduct computerize full wheel allignment.	120.00 <del>NNX</del>
6	1	Spray painting on accident area.	1400.00 600.00
<b>LABOUR TOTAL</b>			<b>4020.00</b>
			1630.00
<b>Total Parts and Labour Cost of Repair</b>			<b>13270.04</b>

Lump sum repair  
 Repair days 5

Parts 2798.08  
 SN 135.00  
 Labour 1630.00  
 4563.08  
 @20% 912.62  
 3650.46

LS 3650/2

NV 2200/2

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	074A
Vehicle Details	
Vehicle No.:	SJP991L
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L15A5207717
Chassis No.:	GJ11306347
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,618.00
Original Registration Date:	11 Mar 2009
First Registration Date:	11 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$16,618.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$4,779.00
<b>Total Rebate Amount:</b>	<b>\$4,779.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Apr 2022

OK

MV 7000/2

PV 4779/2

NV 2221/2

TGlim  
8/4/2022

**MOTOR CAR (LH)**

**Left Portion**

Vehicle No: SJP 991V

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	DP	✓	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1007	992958	Rear Bumper	CUT	✓	
1007	992976	Rear Bumper Bracket			
1008	993068	Rear Bumper Side Retainer	NEG	✓	2
1009	993045	Rear Bumper Reinforcement			
1011	993077	Rear Bumper Sponge			
1015	993040	Rear Bumper Protector			
1015	993026	Rear Bumper Moulding			
1015	993023	Rear Bumper Lower Spoiler			
1016	993851	Rear LH Taillamp	CUT	✓	
1018	993436	Rear LH Fender	DP	✓	
1019	993449	Rear LH Fender Protector			
1038	990247	Sticker			

No of Items: 4 Assessor: T. G. Lin  
 20/12/2002

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 09/12/2021 16:41 (SGT)  
Date of Accident ..... 07/12/2021 08:10 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... UPPER CHANGI ROAD EAST  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SJP991L

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... MUHAMMAD RIZAN YUSRIE BIN YUSOPE  
NRIC No ..... SXXXX074A  
Email Address ..... ryusrie81@gmail.com  
Mobile Phone No ..... (Phone) +65-88836946  
Alternative Phone No ..... +65-88836946

### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Airwave  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1498

### INSURANCE COMPANY

Name of Insurance Company ..... Auto & General Insurance (Singapore) Pte. Limited.  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... P10230949R02  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... MUHAMMAD RIZAN YUSRIE BIN YUSOPE  
NRIC No ..... SXXXX074A

Date Of Birth	22/12/1979
Occupation	Indoor
Date Of Driving Pass	16/10/2008
Driving experience	13 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88836946
Alt. Phone Number	+65-88836946
Email Address	ryusrie81@gmail.com
Address	122 SIMEI STREET 1 #08-430
Address complement	-
Postcode	520122
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Changi Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005872999
Alt. Police Station Phone No	(Fax) +65-65872900
Police Station Address	9 Simei Street 2 Singapore 529914
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED POLICE REPORT T/20211207/2121

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLW1250A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver .....	TAY SOOT LING
Contact Number .....	(Phone) +65-98298000
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	AIG Asia Pacific Insurance Pte. Ltd.
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-

**INJURED PERSONS DETAILS**

INJURED 1

Name of injured person .....	MUHAMMAD RIZAN YUSRIE BIN YUSOPE
Gender .....	-
Phone No .....	-
Address .....	-
Address Complement .....	-
Post Code .....	-
Approximate Age Years Old .....	-
Injuries Sustained .....	FINGER AND BACK PAIN
Injured person in which vehicle? .....	SJP991L
Were seat belts worn? .....	Yes
Was this injured conveyed to hospital by ambulance? .....	No

**Describe Circumstances of the Accident**

as per police report.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
Seiamatshahn

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy benefits.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of the report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data, personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insureds who have insured vehicle(s) involved in this accident (all insureds) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"/lawyers/law firms, the Arbitration Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of any physical packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insureds who have insured vehicle(s) involved in the accident and the Insurers/lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time	 Driver's Signature (if driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Hereafter: Seramatshahia
<p>Sketch Plan</p> <p>A = SJP 9916 B = SLW 1250A</p>  <p>upper Changi road east</p>		