



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: DAVID PHUA

Ref: CS/INC21012613/Gvf3e2

Date: 18/05/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC 1822A	Veh. Inspected	SBW 9870B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1154519-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	14/12/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0025161	Colour	GREY
Odometer	141519 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2021	Inspect Date / Time	14/12/2021 (03:00 PM)
Survey held at	mega@woodlands #01-24		
Repairer	NINETEEN AUTOWERKS PTE. LTD.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**