

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21012618/Dqy3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	20/09/2022	
			Code	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLT 7294A	Veh. Inspected	SHC 887Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010012891/EE	Excess (\$)	0.00	
	Assign From	FIEVEL FOO WEN YAO	Assign Date	14/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ	c.c	1580	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	KMHC851CVLU183671	Colour	YELLOW	
	Odometer	168112 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/12/2021	Inspection Date	14/12/2021	
	Survey held at	Blk 9 Sector C #01-42, Sin Ming	Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

18 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: