



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012619/Kvf3n2	
			Date: 18/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 3429M	Veh. Inspected	SGC 101T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103627/GPL	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	14/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PICNIC (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTEGH23B600026419	Colour	METALLIC MAROON	
Odometer	329870 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	4 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	4 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/12/2021	Inspection Date	14/12/2021	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	