

ASS. REC. BY: SteveREF: C8/A1621012631/EVF3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

XXXX	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMD6350A Yr Regn: 29/8/18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerdo c.c. 1591Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 62633 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAF3416MK5009840Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: ( )

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 11/12/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 14/12/21Cycle & Carriage

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-65K

Date/Time, File Pass to?

☐ : Prell. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/TAN ENG HONG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMD6350A / 29/08/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 52633</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5009840</td></tr> <tr> <td>Engine No</td><td>G4FGJH702480</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>4SS SILKY SILVER / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/TAN ENG HONG	Reg No/Reg Date	SMD6350A / 29/08/201	Date In/Mileage	/ 52633	Chassis No	KNAF3416MK5009840	Engine No	G4FGJH702480	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK
Cust No/Name	/TAN ENG HONG														
Reg No/Reg Date	SMD6350A / 29/08/201														
Date In/Mileage	/ 52633														
Chassis No	KNAF3416MK5009840														
Engine No	G4FGJH702480														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	13/12/2021/ 13:40	BLE	261 / Edwin Caina	43931		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2000.00
RENEW FR BUMPER , FR SUPPORT & BONNET							1800
REPAIR LHF FENDER & RHF FENDER							1400.00
E PNT98000							100.00
RESPRAY FR BUMPER , BONNET , LHF FENDER & RHF FENDER				4			100.00
E PNT88000							80.00
REMOVE & REFIT AC COND & RADIATOR							30.00
M SUNDRY							120.00
TOP UP AC GAS							50.00
A 54900099							120.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM							50.00
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY							40
SUPPLY FR NUMBER PLATE WITH CASING							120.00
M SUNDRY							40
APPLY ANTI CORROSION ON AFFECTED AREAS							80.00
M SUNDRY							20.00
SUPPLY BODY PNL SEALANT							20.00
M SUNDRY							
Sundries							
M LAMP ASSY-HEAD,LH				1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,RH				1.00	1219.00	20.00	975.20
M COVER-FR BUMPER				1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER				1.00	262.00	20.00	209.60
M CAP-FRONT HOOK				1.00	9.00	20.00	7.20
M GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE				1.00	38.00	20.00	30.40
M LAMP ASSY-FRONT FOG,LH				1.00	303.00	20.00	242.40
M LAMP ASSY-FRONT FOG,RH				1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER,LH				1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,RH				1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,LH				1.00	143.00	20.00	114.40

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN ENG HONG Reg No/Reg Date SMD6350A / 29/08/201 Date In/Mileage / 52633 Chassis No KNAF3416MK5009840 Engine No G4FGJH702480 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	13/12/2021/ 13:40	BLE	261 / Edwin Caina	43931
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE REPEATER,RH		1.00	143.00	20.00	114.40
M ABSORBER-FRONT BUMPER ENERGY	BR	1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR		1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60
M BEAM COMPLETE-FR BUMPER	DD	1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE	BR	1.00	675.00	20.00	540.00
M ORNAMENT-KIA NO.115	ACC	1.00	32.00	20.00	25.60
M PANEL ASSY-HOOD	DD	1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH	?	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH	?	1.00	43.00	20.00	34.40
M PAD-HOOD INSULATING	X	1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING PAD MTG	X	13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD	BT	1.00	103.00	20.00	82.40
M CONDENSER ASSY-COOLER	RT	1.00	687.00	20.00	549.60
M GUARD-AIR,LH	BR	1.00	28.00	20.00	22.40
M GUARD-AIR,RH	BR	1.00	28.00	20.00	22.40
M RADIATOR ASSY	?	1.00	646.00	20.00	516.80
M BLOWER ASSY	?	1.00	656.00	20.00	524.80

SURVEYOR NAME : Steve (LKK)  
 SURVEYOR SIGNATURE : 14/12/21, 11:00am  
 DATE : DD-MM  
 REMARKS : Express - ?  
P/P

My B/L Sy  
8 dys

Confirm & accepted by \_\_\_\_\_  
 This is to certify that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

7% GST on **Nett** 12,018.40  
**841.29**  
**Total Payable** 12,859.69

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	13/12/2021 14:16 (SGT)
Date of Accident	11/12/2021 19:18 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE TOWARDS CITY AFTER AMK AVE 1
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6350A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN ENG HONG
NRIC No	SXXXX481B
Email Address	EHTAN2002@YAHOO.COM
Mobile Phone No	(Phone) +65-82825131
Alternative Phone No	+65-82825131

### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800102475-03
Cover Note Number	-

### DRIVER

Name of Driver	TAN ENG HONG
NRIC No	SXXXX481B



Date Of Birth	30/01/1968
Occupation	Indoor
Date Of Driving Pass	05/09/1990
Driving experience	31 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82825131
Alt. Phone Number	+65-82825131
Email Address	EHTAN2002@YAHOO.COM
Address	BLK 241 KIM KEAT LINK #08-197
Address complement	-
Postcode	310241
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	-
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF5083S
Vehicle Manufacturer	BMW
Vehicle Model	520i
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LOKKESH THANGAVELU
Contact Number	(Phone) +65-96487031
Address	-
Address complement	-

Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMN5385G  
Vehicle Manufacturer -  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category Private car  
Name of Driver CHANG SEE SEONG  
Contact Number (Phone) +65-91511797  
Address -  
Address complement -  
Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

x 13/12/21  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

W. Chm  
Witnessed by Reporting Centre Personnel

### Sketch Plan





Describe Circumstances of the Accident

Accident happened on 11/12/21 about 1918hrs  
Travelling back home from Sembrawang via CTE. Wet road  
after rain stop. slow traffic after AMK AVE 1.  
Slow moving traffic diverting to Braddell / PIE exit.  
Travel along lane 1, suddenly saw front vehicles braking,  
immediately ste. tap and brake. Probably due to wet surface  
not able to brake in time and hit onto the front  
vehicle.


Declaration

We declare the foregoing particulars are true in every respect.

✓  13/12/21

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel



## KIA AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : TAN ENG HONG  
**Period of Insurance** : 29 Aug 2021 To 28 Aug 2022  
**Engine No.** : G4FGJH702480  
**Chassis No.** : KNAF3416MK5009840

**Vehicle No.** : SMD6350A  
**Policy No.** : 1800102475-03  
**Endorsement No.** :  
**Issued Date** : 16 Aug 2021

## ABOUT THE COVER

**Make/Model** : KIA Cerato K3 1.6 EX  
**Engine Capacity/Tonnage** : 1,591.00 CC  
**Driver Restriction** : NA  
**Person or Classes of Persons Entitled to Drive\*** :  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2018  
**Insuring with COE/PARF** : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

**Age Condition** : 40 years old and above

**Mileage Condition** : Unlimited Mileage

**Limitation as to use\*** :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

## EXCESS

## Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

## Section 2

Property Damage - \$0

Windscreen : \$100

**Named Driver and Excess** (where applicable)

TAN ENG HONG - \$600 (Own Damage), \$600 (Flood Cover)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan:** Daimler Financial Services Africa & Asia Pacific Ltd

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500760912

CYCLE & CARRIAGE - GARYQ(KIA)

239 ALEXANDRA ROAD

SINGAPORE 159930 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.