

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Ī	Ref:	CS/AGI21012632/Rny3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	I	Date:	14/04/2023	
			(	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLC 3520M	Veh. Inspected		FBD 8086E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012851/EE	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		14/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA T135	c.c		135	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	5YP301025	Colour		MULTI COLOUR	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	60/80-17	MAXXIS		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	70/90-17	MAXXIS		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	08/12/2021	Inspection Date	!	15/12/2021	
	Survey held at	5 SOON LEE STREET #01-38				
	Repairer	CREATION MOTORS				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
	B)IN ACCORDANG	LE TO YOUR INSTRUCTIONS, W	E HAVE NOT AUTE	IUKISE	D REPAIRS.	

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: