

ASS. REC. BY: Steve REF: CS/CT/21012651/EQY3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. SNM21D207239/C02
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 11 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC 105Z Yr Regn: 28/4/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Volkswagen Jetta c.c. 1390
 Colour Red A/C: Insured / Std / NI / NA
 Sp. Reading 75378 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVWZZZ16ZGM-018992
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: NII / S/Rlm / STD A/Rlm or _____
 Tyre Size: F: 205/55R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>4</u> mm	R/Bal. <u>4</u> mm
L/Bal. <u>4</u> mm	L/Bal. <u>4</u> mm
D.O.A. <u>10/12/21</u>	D.O.I. <u>15/12/21</u>

Survey held at Volkswagen
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-52K</u>
	<u>PV-36,184</u>
	<u>NV-15,816</u>
<u>17/12/21</u>	<u>@12.06pm revised to Jenny Lew via Merimen.</u>
<u>29/03/22</u>	<u>@12.41pm checked with Germaine, this case already convert to OD claim.</u>
<u>29/03/22</u>	<u>Submit Preli. report.</u>

Date/Time, File Pass to? ☒ : Preli. Report

1) 29/03 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 11

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL _____

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Tax invoice
Preview

Page

1/3

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
MA
WEILI
807A CHAI CHEE ROAD
#15-04
Singapore 461807

Document no.
Document date 13-12-2021
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 30001
Job order number 2021047217/ 1
Job order date 11-12-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLC105Z	1634G7	28-04-2016	WVWZZZ16ZGM018992	JETTA TSI High 90 D7F	75,164

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B001	TO ALIGN LED HEADLIGHT				#1	100.00	107.00
5C6823031E	Hood	1	pcs.	1,217.06	#1	1,217.06	1,302.25
5C6807217AKGRU	FRT BONNET X R Cover For Bumper Primed X R	1	pcs.	1,363.08	#1	1,363.08	1,458.50
5C6807183A	FRT BUMPER	1	pcs.	37.17	#1	37.17	39.77
5C6807183A	Guide Piece / OR	1	pcs.	37.17	#1	37.17	39.77
5C6807184A	FRT BUMPER SIDE BRACKET LH	1	pcs.	37.17	#1	37.17	39.77
5C6807184A	Guide Piece / OR	1	pcs.	37.17	#1	37.17	39.77
5C8941751B	FRT BUMPER SIDE BRACKET RH	1	pcs.	3,681.62	#1	3,681.62	3,939.33
5C8941751B	Gas Discharge Headlight W / OR	1	pcs.	3,681.62	#1	3,681.62	3,939.33
5C8941752B	LHS H/LAMP	1	pcs.	3,681.62	#1	3,681.62	3,939.33
5C8941752B	Gas Discharge Headlight W / CUT	1	pcs.	3,681.62	#1	3,681.62	3,939.33
5C8941752B	RHS H/LAMP	1	pcs.	3,681.62	#1	3,681.62	3,939.33
1J0973737	Flat Contact Housing With H/LAMP WIRE HOUSING	2	pcs.	21.65	#1	43.30	46.33
5C6821105A	Fender LH / OR	1	pcs.	631.36	#1	631.36	675.56
5C6821105A	LH	1	pcs.	51.67	#1	51.67	55.29
5C6821135	Cross Support	1	pcs.	51.67	#1	51.67	55.29
5C6821135	LHS FENDER BRACKET / MC	1	pcs.	185.93	#1	185.93	198.95
5C6805911N	Wheelhouse Liner X NN	1	pcs.	185.93	#1	185.93	198.95
5C6805911N	LHS FENDER LINER	1	pcs.	631.36	#1	631.36	675.56
5C6821106A	Fender RH / OR	1	pcs.	631.36	#1	631.36	675.56
5C6821106A	RH	1	pcs.	51.67	#1	51.67	55.29
5C6821136	Cross Support	1	pcs.	51.67	#1	51.67	55.29
5C6821136	RHS FENDER BRACKET / MC	1	pcs.	185.93	#1	185.93	198.95
5C6805912N	Wheelhouse Liner / CRH	1	pcs.	185.93	#1	185.93	198.95
5C6805912N	RHS FENDER LINER	1	pcs.	185.93	#1	185.93	198.95
WHT004694	Expanding Nut / MC	6	pcs.	1.84	#1	11.04	11.81
5C6853630F ULM	Vw Sign Chrome Colored/BI	1	pcs.	99.29	#1	99.29	106.24
5C6853687 739	REAR BOOT LID NAME PLATE - VW	1	pcs.	70.95	#1	70.95	75.92
5C6853687 739	Inscription Brilliant Chr	1	pcs.	70.95	#1	70.95	75.92
5C6853687 739	NAME PLATE - JETTA / MC	1	pcs.	65.63	#1	65.63	70.22
1K9853675B GQF	Inscription Chrome/Red / MC	1	pcs.	65.63	#1	65.63	70.22
1K9853675B GQF	NAME PLATE - TSI / MC	1	pcs.	65.63	#1	65.63	70.22
5C6807421H GRU	Cover For Bumper Primed / OR	1	pcs.	1,359.58	#1	1,359.58	1,454.75
5C6807421H GRU	REAR BUMPER	1	pcs.	17.03	#1	17.03	18.22
5C6919491D	Sensor Bracket / MC	1	pcs.	17.03	#1	17.03	18.22
5C6919491E	Sensor Bracket / MC	2	pcs.	17.03	#1	34.06	36.44
5C6919492D	Sensor Bracket / MC	1	pcs.	17.03	#1	17.03	18.22
5C6919492D	Sensor Bracket / MC	1	pcs.	73.08	#1	73.08	78.20
D 180KD2A1	2-Pack Polyurethane Adhes / MC	1	pcs.	65.42	#1	65.42	70.00
D 822150A1	Bonding Agent For Plastic / BR	1	pcs.	504.36	#1	504.36	539.67
5C6807433J	Spoiler	1	pcs.	504.36	#1	504.36	539.67

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice Preview

Page

2/3

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
MA
WEILI
807A CHAI CHEE ROAD
#15-04
Singapore 461807

Document no.
Document date 13-12-2021
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 30001
Job order number 2021047217/ 1
Job order date 11-12-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLC105Z	1634G7	28-04-2016	WVWZZZ16ZGM018992	JETTA TSI High 90 D7F	75,164

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5C6807305	Bumper REINFORCEMENT	1	pcs.	652.80	#1	652.80	698.50
5C6807863B	Attachment Strip	1	pcs.	85.30	#1	85.30	91.27
5C6807393E	RR BUMPER CTR BRACKET	1	pcs.	91.69	#1	91.69	98.11
5C6807394E	Guide Piece	1	pcs.	91.69	#1	91.69	98.11
5C6807375	LHR BUMPER BRACKET (UPPER)	1	pcs.	91.69	#1	91.69	98.11
5C6807376	Guide Piece	1	pcs.	91.69	#1	91.69	98.11
5C6945095N	LHR BUMPER BRACKET (SIDE)	1	pcs.	91.69	#1	91.69	98.11
5C6945105B	Guide Piece	1	pcs.	91.69	#1	91.69	98.11
5C6253609J	Taillight	1	pcs.	442.71	#1	442.71	473.70
1K0253141M	LHS TAILLIGHT OUTER	1	pcs.	75.29	#1	75.29	80.56
	Reflector	1	pcs.	75.29	#1	75.29	80.56
	LHS REFLECTOR	1	pcs.	1,500.51	#1	1,500.51	1,605.55
	Exhaust Silencer Rear	1	pcs.	62.35	#1	62.35	66.71
	Dual Clamp	1	pcs.	195.00	#1	195.00	208.65
	Towing assistance - AWP	1	pcs.	840.00	#1	4,200.00	4,494.00
	LABOUR FRT	8	pcs.	800.00	#1	4,000.00	4,280.00
	SPRAY PAINT FRT	8	pcs.	840.00	#1	4,200.00	4,494.00
	LABOUR REAR	5	pcs.	800.00	#1	4,000.00	4,280.00
	SPRAY PAINT REAR	5	pcs.	800.00	#1	4,000.00	4,280.00
	MSIG MOTORMAX PLUS VS CHINA						
	TAIPING						
	3RD PARTY VEHICLE SJK2614P						
	D.O.A: 10-12-2021						

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	860.00	33,897.13	7%	2,433.00	34,757.13	37,190.13
Total	860.00	33,897.13		2,433.00	34,757.13	37,190.13

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

Acknowledged by Repairer
Signature:
Date:

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice Preview

Page 3/3

Document no.	
Document date	13-12-2021
Customer no.	5211001211
Customer GST-ID	200412212G
Dealer	30001
Job order number	2021047217/ 1
Job order date	11-12-2021
Service Advisor	YEN MEI WONG

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
MA
WEILI
807A CHAI CHEE ROAD
#15-04
Singapore 461807

License plate	Model code	First registration	VIN	Model	Mileage
SLC105Z	1634G7	28-04-2016	WVWZZZ16ZGM018992	JETTA TSI High 90 D7F	75,164

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

This is an authorised document. No signature is required.

All invoices are denominated in SGD, unless otherwise stated.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/12/2021 10:17 (SGT)
Date of Accident	10/12/2021 19:20 (SGT)
Exact Location of Accident	ECP, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC105Z
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MA WEILI
NRIC No	SXXXX3011
Email Address	maweili@gmail.com
Mobile Phone No	(Phone) +65-98210677
Alternative Phone No	+65-98210677

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Jetta
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1390

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	A 300307461 QMY
Cover Note Number	-

DRIVER

Name of Driver	MA WEILI
NRIC No	SXXXX3011

Date Of Birth	01/03/1982
Occupation	Indoor
Date Of Driving Pass	25/07/2003
Driving experience	18 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98210677
Alt. Phone Number	+65-98210677
Email Address	maweil@gmail.com
Address	25 WEST COAST RISE #04-08
Address complement	-
Postcode	127468
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	DRIZZLING
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	NOT APPLICABLE
Gender	Male

PASSENGER 2

Name	NOT APPLICABLE
Gender	Female

PASSENGER 3

Name	NOT APPLICABLE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 10/12/21 AROUND 1920 HRS, I WAS DRIVING ALONG ECP TOWARDS CHANGI ON THE 1ST LANE. VEHICLE B IN FRONT OF ME SUDDENLY BRAKED. I BRAKE IMMEDIATELY AND SWERVE TO THE RIGHT AND HIT ONTO VEHICLE B REAR RIGHT. SECONDS LATER, I FELT AN IMPACT FROM BEHIND AND MY VEHICLE SURGE FORWARD. I ALIGHTED FROM MY CAR TO CHECK AND REALIZED VEHICLE C COLLIDED INTO MY VEHICLE REAR PORTION. I WAS INVOLVED IN A 3 CARS CHAIN COLLISION.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----



Accident report SF0D21CB0002

Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX656B
Vehicle Manufacturer	Toyota
Vehicle Model	Harrier
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEH B
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJK2614P
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	RANDY
NRIC No	SXXXX912E
Contact Number	(Phone) +65-96673820
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEH C
No. Of Passenger (Including Driver)	1

SKETCH PLAN



A - SKC105E

B - SKX 656B

C - SJR 2614P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/12/21 around 1920 hrs, I was driving along ECP towards Chungs on the first lane.

Vehicle B in front of me suddenly braked. I brake immediately & swerve to the right & hit onto vehicle B rear right. Seconds later, I felt an impact from behind and my vehicle surge forward.

I alighted from my car to check & realised vehicle C collided into my vehicle rear portion. I was involved in a 3-car chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

MA WEI LI
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz

Worldwide Partners

Date: 10/12/91 Time: 2055
 Technician Name: FOOK 985903
 Reg. No: 92C1052 Job No: V231003546
 Odometer Reading (Customer Vehicle):
 KM Travelled by Assistance Vehicle: (1 way)
 Fault Reported: ACCIDENT
 Fault Found:
 How was vehicle repaired?

Customer Name: MR GUEK
 Customer Telephone: 90307120
 Make/Model: JETTA
 Location: 51 MARINE TERRACE
 Time on Scene: 2118
 Time Job Completed: 2140
 Repaired at Breakdown Scene: Y/N
 VIN No:

Hubcaps Y/N

Spare Wheel Y/N

Tools Y/N

Audio System Y/N

Keys + Remote Y/N

Aerial Y/N

Cashcard Y/N

Fuel

E		F
---	--	---

Interior Condition :

Front Seats

Rear Seats

Floor Covering

Headlining



Day/Night

Wet/Dry

Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent



Delivery to Dealership / Date and Time:

247 ALBY RD 10/12/91 2215

Vehicle received in the above condition YES/NO

If not stated as above specify difference:

CUSTOMER DECLARATION

1. I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
2. I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
3. In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
4. I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customer Name & Signature (green copy)	<u>MA WILLY</u>	Dealer/Workshop Signature, Name & Stamp (yellow copy)	<u>A. At</u>	Operators Signature (white & pink copy)	<u>[Signature]</u>
--	-----------------	---	--------------	---	--------------------