ASS. Filed By: GQ | REF: CS/ASM21012655/Gvy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s H S AUTO

of

Insured: SHC 1883B

Policy No.

Claims No. S1M03O2U

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $39k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGY9640D Yr Regn: 15 Oct/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 c.c 1598

Colour Beige A/C: Insured / Std / NI / NA

Sp.Reading 152623 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053ZEC107156310 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/70R14

R: 185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or KAPSEN

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 11/12/2021 D.O.I. 15-12-2021

Survey held at W/S 12PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/3/22	Guo Qiang informed LS $9150 (Red 11,475.85, 55%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 19/5/22-typist

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format: TP

Lump Sum / UPD: LS $9150

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL