



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KIA/CERATO 1.6 A SR SX G335.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account details for LAX00000 and operator Edwin Caina.

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like bumper, fender, and electrical system work with handwritten notes and a large 'Estimate' watermark.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle specifications for a KIA CERATO 1.6 A SR SX G335.

Table with 7 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No, Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts and their estimated costs.

Estimate

SURVEYOR NAME: Steve (LKK) 15/12/21, 9-30am
SURVEYOR SIGNATURE: OO-M PL
DATE: EXCISE-?
REMARKS: PIP
My Belly
4 dys

LKK Auto Consultants hence notify the Repairer of the following.

- Confirm & accepted by after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Summary table showing Net amount of 11,856.00, 7% GST on 11856.00 resulting in 829.92, and Total Payable of 12,685.92.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.