



CYCLE & CARRIAGE

ALG - OD CLAIM
SURVEY: 15/12/21

UKK - STEVE

VEHICLE NO : SMG8808T

MODEL : KIA/CERATO 1.6 A SX

WIP : 43985

Material	:	\$	<u>2,656.00</u>
Labour	:	\$	<u>2,860.00</u>
Sub-Total	:	\$	<u>5,516.00</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>5,216.00</u>
GST 7%	:	\$	<u>365.12</u>
Grand Total	:	\$	<u>5,581.12</u>
Finalise By/Date	:	<u>LATHY ON 31/12/21</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk. end)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 15/12/2021	Cust No/Name	LCV08555/LIU JUNLIN
	Reg No/Reg Date	SMG8808T*KC17/ 20/02/2019
	Date In/Mileage	15/12/2021/ 38124
	Chassis/Package	KNAF3416MK503088E /#
	Engine No	G4FGJH720904
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	30/12/2021/ 16:13	BLE	884 / Lauro Songcuan	43985
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 RENEW FRONT BUMPER & BONNET, REPAIR LH FRONT FENDER & RH FRONT FENDER					600.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER, BONNET, LH FRONT FENDER & RH FRONT FENDER					1920.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00 ✓
E PNT88000 REMOVE & REFIT FRONT PARKING ASSIST SENSOR					80.00 ✓
M SUNDRY SUPPLY BODY PANEL SEALANT					40.00 ✓
M SUNDRY SUNDRIES					20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)					50.00 ✓
X EXC EXCESS					-300.00
X PANEL ASSY-HOOD ✓	1.00	1502.00	20.00		1201.60 ✓
X HINGE ASSY-HOOD,LH ?	1.00	43.00	20.00		34.40 ?
X HINGE ASSY-HOOD,RH ?	1.00	43.00	20.00		34.40 ?
X GARNISH-RADIATOR GRILLE ✓	1.00	38.00	20.00		30.40 ✓
X GRILLE ASSY-RADIATOR ✓	1.00	328.00	20.00		262.40 ✓
X COVER-FR BUMPER ✓	1.00	633.00	20.00		506.40 ✓
X GRILLE-FRONT BUMPER ?	1.00	485.00	20.00		388.00 ?
X MOULDING-FRONT BUMPER,LH ✓	1.00	216.00	20.00		172.80 ✓
X ORNAMENT-KIA NO.115 ✓	1.00	32.00	20.00		25.60 ✓
Z TEXT AIG - OD CLAIM SURVEY: STEVE (LKK) 15/12/2021 DOA: 13/12/2021 04 DAYS					
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>					

Parts	2,656.00		Nett	5,216.00
Labour	2,750.00			
Standard Menu	0.00	7% GST on	5216.00	365.12
Specialist Job	50.00			
Diagnostics Job	0.00		Total Payable	5,581.12
Sundry/Others	-240.00			
Total(w/o GST)	5,216.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

CAR NO: SMG 8808T

WIP: 43985

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	RRR <u>RRR</u> RRR <u>RRR</u>	? / SUPP			86530 m 6160
2	LH HINGE	? / SUPP			66910 m 6000
3	RA HINGE	? / SUPP			66920 m 6000
4	<u>Rump gild find (DRK)</u>	? / SUPP		<u>Steve</u> <u>20/10/21</u>	
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	20/12	Steve whatsup
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATO

SURVEYOR: STEVE



e-Report [Pilot Ver : 1.064]_20211209



KNAF3416MK5030888 CERATO/FORTE(BD)/2019/G 1.6 MPI GAMMA



e-Report

e-Report Case Statistics

eReport Case View

Vehicle Diagnosis Number : 2112280631

List

Prev Page

Date	12/28/2021	Distributor	A22VA	Dealer Code	00001
ServerDate	12/28/2021	Model	CERATO/FORTE(BD)	Engine Type	G 1.6 MPI GAMMA
GDS Version	Source : Content :	Selected Symptom		VIN	KNAF3416MK5030888

Vehicle Information	Unchecked	Warranty History	Unchecked
---------------------	-----------	------------------	-----------

odometer - Information			
odometer	Unit	VCI	
38125	km	VCI2_WFD	

Total Count : 1

Diagnosis - DTC Codes					
Type	System	Code	Description	FreezeFrame Status	VCI
Fault Code Searching	Engine		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Transmission		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Brake		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Steering		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Airbag		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Air Conditioner		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Rear View Monitor		Communication Fail / Check whether system is installed or not. Check the IG key and DLC.		VCI2_WFD
Fault Code Searching	Cluster Module		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Integrated Body Control Unit-B CM		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Integrated Body Control Unit-I MMO		Communication Fail / Check whether system is installed or not. Check the IG key and DLC.		VCI2_WFD
Fault Code Searching	Integrated Body Control Unit-S MK		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Power Seat		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Wireless Power Charger		No DTC present at this time.	-	VCI2_WFD
Fault Code Searching	Integrated Central Control Unit		No DTC present at this time.	-	VCI2_WFD

Total Count : 14

S/W Ver.

NEK-00-0009

VCI Ver.

02.63

Res Ver.

NEK-00-0009

OS Ver.

Android 11



e-Report [Pilot Ver : 1.064]_20211209



KNAF3416MK5030888 CERATO/FORTE(BD)/2019/G 1.6 MPI GAMMA



e-Report

e-Report Case Statistics

eReport Case View

Vehicle Diagnosis Number : 2112280631

List Prev Page

Date	12/28/2021	Distributor	A22VA	Dealer Code	00001
ServerDate	12/28/2021	Model	CERATO/FORTE(BD)	Engine Type	G 1.6 MPI GAMMA
GDS Version	Source : Content :	Selected Symptom		VIN	KNAF3416MK5030888

Vehicle Information	Unchecked	Warranty History	Unchecked
---------------------	-----------	------------------	-----------

odometer - Information			
odometer	Unit	VCI	
38125	km	VCI2_WFD	

Total Count : 1

Diagnosis - DTC Codes						
Type	System	Code	Description	FreezeFrameStatus	VCI	
Fault Code Searching	Engine		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Transmission		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Brake		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Steering		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Airbag		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Air Conditioner		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Rear View Monitor		Communication Fail / Check whether system is installed or not. Check the IC key and DLC.	-	VCI2_WFD	
Fault Code Searching	Cluster Module		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Integrated Body Control Unit-B CM		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Integrated Body Control Unit-H MMO		Communication Fail / Check whether system is installed or not. Check the IG key and DLC.	-	VCI2_WFD	
Fault Code Searching	Integrated Body Control Unit-S MK		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Power Seat		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Wireless Power Charger		No DTC present at this time.	-	VCI2_WFD	
Fault Code Searching	Integrated Central Control Unit		No DTC present at this time.	-	VCI2_WFD	

Total Count : 14

S/W Ver.

NEK-00-0009

VCI Ver.

02.63

Res Ver.

NEK-00-0009

OS Ver.

Android 11



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KIA CERATO 1.6 A SR SX G335.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX00000, Credit, 14/12/2021/ 12:53, BLE, 261 / Edwin Caina, 43985

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like bumper, fender, AC cond, radiator, electrical system, etc. Includes handwritten notes and a large 'Estimate' watermark.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KIA CERATO 1.6 A SR SX G335.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX00000, Credit, 14/12/2021/ 12:53, BLE, 261 / Edwin Caina, 43985

Table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like BRACKET-FR BUMPER, WIRING ASSY, MOULDING-FRONT BUMPER, LAMP ASSY, etc.

Estimate

SURVEYOR NAME : Steve (LKK) 15/12/21, 9-30am

SURVEYOR SIGNATURE : [Signature]

DATE : EXCIS - ?

REMARKS : PIP, My Belly, 4 dys

Confirm & accepted by

Summary table with columns for Net, 7% GST on, Total Payable and corresponding amounts: 11,856.00, 829.92, 12,685.92

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.