

**COMFORTDELGRO**  
**ENGINEERING**

**ComfortDelGro Engineering Pte Ltd**  
59 Loyang Drive Singapore 508969

Our Ref : 305497834  
Date : 14.12.21  
Time of Fax :                     

Via Fax : EMAH  
Your Insured : SJU 1898R  
Date of Acc : 11.12.21

Attn: Motor Claims Department ALG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A9807E**

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

- ◆ Lim Kwok Eng                      Tel: 6214 8355 or HP: 9824 0811
- ◆ Jumani Bin Masudin              Tel: 6214 8315 or HP: 9635 5305
- ◆ Lim Tien Siong                      Tel: 6214 8398 or HP: 9635 8546
- ◆ Chiang Liat Choon              Tel: 6214 8314 or HP: 9296 6006

} **chianglc@cde.com.sg**  
} **Fax no. 6546 8156**

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully



For Vice President  
Taxi Accident Repair

**REPAIR ESTIMATE\***

VEHICLE NO **SHA9807E**

DATE **11/12/2021 1820**

MAKE **REG 27.08.2020**

MODEL **: HYUNDAI IONIQ G3**

**CHIANG/AIG**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT RH WING MIRROR			\$1,391.70
	<b>SUB TOTAL</b>			<b>\$1,391.70</b>
	<b>LESS 20%</b>			<b>\$278.34</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,113.02</b>
	<b>Labour Charge</b>			
	Panel Beating			\$120.00
	Spray Painting Charge			\$100.00
	<b>TOTAL LABOUR</b>			<b>\$220.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$1,333.02</b>
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				