

Our Job Ref No : 305497834
 Date : 15/12/21

ENGINEERING
 ComfortDelGro Engineering Pte Ltd
 59 Loyang Drive Singapore 508969
 Fax: 6546 8156

FINALIZATION FORM

To : LKK
 Attn : THEVAN
 Vehicle Reg No. : SHA9807E

Fax : _____
11/12/21


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SJU1898R
2. The finalized amount shall be:

(a) Spare Parts after List discount	
(b) Labour Charges	\$160.00
Total for Part-By-Part Repair Cost	\$160.00
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
Final Lumpsum Repair cost	
3. Estimated normal period for repairs: 1 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance. We confirm the estimates and finalized amount

<p>Signature : </p> <p>Name : <u>CHIANG</u></p> <p>Tel : <u>62148314</u></p> <p>Fax : <u>65468156</u></p>	<p>Signature : </p> <p>Name : <u>THEVAN</u></p> <p>Date : <u>17/12/21</u></p>
---	---

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: _____

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 15.12.2021
Time: 14:36:37
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305497834
REGN NO : SHA9807E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 27.08.2020
DATE/TIME IN : 13.12.2021 13:50
ACCIDENT DATE : 11.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING SHA9807E	80.00
0001 SP	SPRAYPAINT CHARGE	80.00

SUB-TOTAL : 160.00

TOTAL : 160.00

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

NAME & SIGNATURE

DATE :

1 day

REPAIR ESTIMATE*

VEH NO SHA9807E

DATE 11/12/2021 1820

MAK REG 27.08.2020

MODEL : HYUNDAI IONIQ G3

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT RH WING MIRROR			\$1,391.70 <i>Kr</i>
	SUB TOTAL			\$1,391.70
	LESS 20%			\$278.34
	DISCOUNTED TOTAL			\$1,113.02 ✓
	Labour Charge			
	Panel Beating			\$120.00 <i>80</i>
	Spray Painting Charge			\$100.00 <i>80</i>
	TOTAL LABOUR			\$220.00 ✓
	ESTIMATE TOTAL			\$1,333.02

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevanellkhandu.com
482235769
11/12/21 1700
PIP btr paint photo
Labour only
1 day w/p

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: