

Apur (Usum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.12.2021

Time: 12:25:26

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305497684
REGN NO : SHC7633S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 13.12.2021 09:05
ACCIDENT DATE : 11.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1	459.40	20.00	367.52	de ✓	
0002 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	ant ✓	
0003 04-01-0101-0111-G BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	ner ✓	932.65
0004 04-01-0104-0852-G REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	XUN ✓	786.12
SUB-TOTAL :						771.72

JOB NATURE

0000 PB	PANEL BEATING	400.00	350	
0001 SP	SPRAYPAINT CHARGE	300.00	250	
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30	630
SUB-TOTAL :		750.00		1376.12
TOTAL :		1,521.72		2459.84

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanfhir 97495749
UP 13/12/21 @ 330
22 days
43 Resurvey after repair
Tanfhir @ (LKK Auto Consultants)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: