



Service Request Details

Claim

S1M03OEW

Reference

CS3/ASM21012701/y3 

Loss Date

14 December 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

15 Dec 2021 8:58:37 AM

Request Date

15 December 2021

Due Date

22 December 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)

Vehicle Information

Incident Vehicle Registration #
GBK7029R

Make
TPVD Toyota

Model
Hiace

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KOH Janice

janice.kohlc@axa.com.sg
Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics


Notes

New Message

TYPE	
SENT	15/12/21 2:11 PM

BODY

Noted with thanks. Please be informed that vehicle...



TYPE

?

SENT

15/12/21 1:55 PM

FROM


KOH Janice

SUBJECT

Re:WORKSHOP DETAIL

BODY

Kim Seng Teck Motor Works Block 3021A Ubi Road 1...



TYPE

?

SENT

15/12/21 10:44 AM

FROM


LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

WORKSHOP DETAIL

BODY

Dear Janice, Thank you for the assignment. Please ...



https://vendor.smartclaims.axa.com.sg/ClaimApplication/dist/html/index-vendor.html#/service-requests/?serviceRequestNumber=241283

3/3