



Service Requests

Messages

Claims



Service Request Details

Claim	S1M03OEW
Reference	CS3/ASM21012701/Vvy3e2 
Loss Date	14 December 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	15 Dec 2021 8:58:37 AM
Request Date	15 December 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	GBK7029R
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Hiace

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KOH Janice

janice.kohl@axa.com.sg

Additional Instructions

Messages3InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2108836.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2021
 GBK 7029R IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 December 2021
 GBK 7029R LKKPhotos RES.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 December 2021
 GBK 7029R LKKPhotosIn4.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 December 2021
 EMAIL FORM SOLICIOTR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	15 December 2021
 GBK7029R TP GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	15 December 2021