FAQ English (SG) ▼ Elaine Kuan ▼

Service Requests •••

Claim S1M03OED

Reference CS3/ASM21012712/Eqy3e2

Loss Date 12 December 2021

Vendor Name LKK AUTO CONSULTANTS

PTE LTD (TP)


Type of Loss Third Party Vehicle Damage

Report Date 14 Dec 2021 5:49:02 PM

Request Date 15 December 2021

Due Date

Services Pre-Repair Survey



Vehicle Information

Incident XD7656G

Vehicle

Registration #

Make TPVD

Model Isuzu

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

