



Service Request Details

Claim

S1M03OED

Reference

CS3/ASM21012712/Eqy3 

Loss Date

12 December 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

14 Dec 2021 5:49:02 PM

Request Date

15 December 2021

Due Date

22 December 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)

Vehicle Information

Incident Vehicle Registration #
XD7656G

Make
TPVD

Model
Isuzu

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TAN Jun Hong

junhong.tan@axa.com.sg
Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document SubType

▼

 Upload Documents

Already Attached

NAME	 PRI TP EMAIL PDF.pdf.pdf
TYPE	Other
SUBTYPE	Other
AUTHOR	do not reply
DATE UPLOADED	

NAME	 REPLY FROM TP.msg.msg
TYPE	Letters and Correspondence
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE UPLOADED	15 December 2021

NAME	 PRI TP EMAIL.msg.msg
TYPE	Letters and Correspondence
SUBTYPE	Workshop
AUTHOR	KUMAR Shailendra
DATE UPLOADED	15 December 2021

NAME	 XD7656G TP GIA.pdf.pdf
TYPE	Letters and Correspondence
SUBTYPE	Workshop
AUTHOR	KUMAR Shailendra
DATE UPLOADED	15 December 2021

NAME	 PRI TP EMAIL PDF.pdf.pdf
TYPE	Letters and Correspondence

DATE UPLOADED	15 December 2021
NAME	 SJ0421CD000C-SHD7250H.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	Accident statement
AUTHOR	STACEY Ng Pei Sze 2
DATE UPLOADED	14 December 2021