



Your Ref: S1M03NHZ

Date: 27th Dec 2021

Our Ref: CS3/ASM21012296/Vqy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way
#24-01 Axa Tower
Singapore 068811
(The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFR 5087B
INSURED VEHICLE: SH 8765G
ACCIDENT DATE: 02/12/2021**

We thank you for your instruction on 02/12/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFR 5087B from M/s RW Automotive Appraisers Services.
- b) Singapore Accident Statement of Vehicle SFR 5087B and SH 8765G.
- c) Police Report of Vehicle SFR 5087B
- d) Colour damaged vehicle photographs of SFR 5087B.

Pre-Repair Inspection Date : 06/12/2021 at M/s Dreamworks Garage, 25 Kaki Bukit Road 4, #06-55, Synergy @ KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|---|
| Registration Number | : SFR 5087B |
| Make & Model | : Hyundai I45 2.0 AT ABS Airbag 2WD 4DR |
| Year of Registration | : 2011 |
| Chassis Number | : KMHEC41BMBA253404 |
| Engine Capacity | : 1998 cc |

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.