



Claim	S1M03OF8
Reference	CS3/ASM21012714/Tqy3e2 
Loss Date	11 December 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	15 Dec 2021 9:46:55 AM
Request Date	15 December 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SLG4897Z
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Isis

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188



Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
SKETCH.png.PNG	Other	Other	do not reply	
ASM-LKKInvoice-AC2200552.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022

FAQ English (SG) ▾ Elaine Kuan ▾			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	...	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022
	 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022	
	 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	28 January 2022	
	 AXA Immediate Advice - SLG4897Z (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2022	
	 OI FRONT VIDEO.mp4	Evidence	Videos	TEO Kitty	22 December 2021	
	 OI GIA RPT (SHA7813A).pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	15 December 2021	
	 TP GIA RPT (SLG4897Z).pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	15 December 2021	

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)

SUBTYPE

AUTHOR

DATE
UPLOADED[Service Requests](#)[ers and
Correspondence](#)

Others

NIKAM Santosh Pandurang

15
December
2021[ACK TO TP.msg.msg](#)[Letters and
Correspondence](#)

Others

NIKAM Santosh Pandurang

15
December
2021