



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref: CS3/ASM21004347/Rty3e2-1
8 SHENTON WAY #24-01 AXA TOWER	Date: 22/02/2022
SINGAPORE 068811	
ATTN: CHAN KIAN CHUAN	Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SHB 4245D	Veh. Inspected	YN 3284H
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S1M036YL	Excess (\$)	0.00
Assign From	CHAN KIAN CHUAN	Assign Date	16/12/2021

2. Vehicle Particulars & Condition

Make & Model	HINO GH8JRKA	c.c	7684
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	GH8JRK12575	Colour	WHITE
Odometer	326026 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	10.00 R20	LONG MARCH	7 mm
L/H Front Tyre	10.00 R20	LONG MARCH	7 mm
R/H Rear Tyre	10.00 R20 (D)	LONG MARCH	7/7 mm
L/H Rear Tyre	10.00 R20 (D)	LONG MARCH	7/7 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	31/03/2021	Inspection Date	27/12/2021
Survey held at	7 PENJURU CLOSE		
Repairer	VFIX AUTO SERVICE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**