

ASS. REC. BY:

REF:

A/G 21012737/K+

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

L17mk

of

Insured:

4210

Policy No. 1800003488-02

Claims No. 4595042732SG

Sum Insured:

Excess:

1000 ?

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

878k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 27344

Yr Regn:

12, 17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo

V40 T2

c.c.

1498

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

23707

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YVIMV2820J2481184

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

205/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

6/12/21

D.O.I.

17/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

 15,769.13 IN CLUSIVE MERIMEN FEE \$11
RED; NO REDUCTION.

Data/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Data/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

500

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: 1800003488-02
Repairer Reference: 72390
Date calculated: 08/12/2021 5:05 PM

Full Report
Registration: SLV 2734U
Printed: 08/12/2021 5:06 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	1800003488-02	Date of Incident:	06/12/21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: VOLVO
Model: V40 (M)
Sub Model: BASE MODEL
Model Sheet Number: 41 29 01
Registration: SLV 2734U

VIN number:
Odometer: 23706

Model Specs

1.5 LTR 90 KW FRONT DRIVE TYRES 205/55 R16..V TWO COAT METALLIC
PREPARE OFF VEHICLE

*Not Authorized
Repairer B4PQINT*

Labour

Code	Description	Time Base 10 WU/h	Price = 48.00 SGD/h	
			WU	Price SGD
80205-0	RENEW FRONT PANEL AND R/WING INCLUDES: R + R BUMPER, HEADLAMPS, WING, FRONT WHEELHOUSE COVER, WHEEL AND FRONT PANEL, ADJUST HEADLAMPS		22.0	105.60
86170-2)	R + R ATTACHED PARTS OF THE BUMPER		12.0	57.60
82151-2	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		6.0	28.80
82131-2	ADJUST BONNET		3.0	14.40
85120-2	R + R RIGHT FRONT DOOR TRIM		2.0	9.60
84530-2)	R + R R/FRT WINDOW RAIL DOOR		5.0	24.00
NO NUMBER	R + R R/F DOOR TRIM		1.0	4.80
84122-2	R + R R/F SIDE WINDOW TRIM		1.0	4.80
83404-2	R + R OUTER HANDLE R/FRONT DOOR		3.0	14.40
84623-2	R + R RIGHT DOOR MIRROR GLASS		1.0	4.80
84625-2)	R + R R/DOOR MIRROR COVER		1.0	4.80
83412-2	R + R R/R OUTER DOOR HANDLE		3.0	14.40

Code	Description	WU	Price SGD
NO NUMBER	R + R R/R DOOR TRIM FRONT	1.0	4.80
NO NUMBER	R + R R/R DOOR FRAME TRIM REAR	1.0	4.80
77223-3	R + R RIGHT FRONT TYRE	2.0	9.60
77077-3	R/FRONT WHEEL BALANCE	1.0	4.80
1482	RIGHT FRONT DOOR REPAIR	15 20.0*	96.00
2406	R/OUTER ROOF FRAME REPAIR	25 30.0*	144.00
1002	R/F WHEEL RIM REPAIR	20 30.0*	144.00
<i>Already repaired</i>			
Labour Cost		Hrs	WU
Panel / Mechanical Labour		14.50	145.0
Total of Labour			696.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	25.0	
	R/F WING NEW PART PAINTING	9.0	
	FRONT PANEL SURFACE PAINT	5.0	
	FRONT BUMPER NEW PART PAINT K1R	13.0	
	RIGHT MIRROR COVER NEW PART PAINT K1R	3.0	
	R/SILL PANEL COVER NEW PART PAINT K1R	7.0	
	RIGHT FRONT DOOR REPAIR PAINTING <50%	16.0	
	R/OUTER ROOF FRAME REPAIR PAINTING <50%	8.0	
	FRT TOWING EYE COVER SURFACE PAINT PLAST.	3.0	
	R/R DOOR SURFACE PAINT	7.0	
	R/RR SIDE PANEL SURFACE PAINT	6.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	84.62
0742	R/F WING NEW PART PAINTING	15.48
1017	FRONT PANEL SURFACE PAINT	8.47
0283	FRONT BUMPER NEW PART PAINT K1R	64.45
1746	RIGHT MIRROR COVER NEW PART PAINT K1R	2.95
2208	R/SILL PANEL COVER NEW PART PAINT K1R	29.03
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	27.46
2406	R/OUTER ROOF FRAME REPAIR PAINTING <50%	4.85
0303	FRT TOWING EYE COVER SURFACE PAINT PLAST.	0.37
1782	R/R DOOR SURFACE PAINT	17.43
3482	R/RR SIDE PANEL SURFACE PAINT	13.94

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	48.00 SGD/h			
Time Paint			102.0	
Preparation Main Work Metal		2.50	25.0	120.00
Preparation Comp. Work Plastic		0.50	5.0	24.00
Total	10 WU/h	13.20	132.0	633.60

Material Cost - Paint

New Part Painting	
New Part Painting - Plastic K1R	
Repair Painting	
Surface-/Blend Paint	
Surface Painting Plastic	
Material-constant Metal Preparation	
Material-constant Plastic	
Total	

Price SGD
100.10
96.43
32.31
39.84
0.37
28.60
9.00
306.65

Spare Parts

				prices as at 2001-01-01	
Code	Description	Part Number	Part Source		Price SGD
0471	BONNET	31424258	Original	PA ✓	2,448.00
8783	ENGINE COMP INSUL	31440279	Original	Del / GA ✓	297.00
0283	FRONT BUMPER	39820367	Original	CM ✓	1,581.00
1017	FRONT PANEL	31416490	Original	CM ✓	1,776.00
0371	FRT LOWER AIR GUIDE	31455220	Original	7	193.00
1738	R/DOOR MIRROR	31299639	Original	PA ✓	606.00
1744	R/DOOR MIRROR GLASS	30716483	Original	GA ✓	260.00
1658	R/F DOOR TRIM	31463560	Original	SWU Sen repair	183.00 X
7228	R/FR TYRE	205/55 R 16 .. V	Original	Repair	0.00
1640	R/F SIDE WINDOW TRIM	31278546	Original	PA Del ✓	72.00
1598	R/F WINDOW CHANNEL	31371807	Original	GA ✓	136.00
0742	R/F WING	31301262	Original	BE ✓	1,083.00
1958	R/R DOOR TRIM FRONT	31391186	Original	Sen SWU repair	183.00
1960	R/R DOOR TRIM REAR	31391188	Original	Sen SWU repair	183.00
2208	R/SILL PANEL COVER	39834378	Original	CM ✓	530.00
1430	R/WINDSCREEN SEAL	31378573	Original	Del / GA ✓	166.00
0562	RIGHT HEADLAMP ASSY	31283329	Original	BE ✓	1,640.00
1746	RIGHT MIRROR COVER	39850553	Original	mi ✓	298.00
					0.00
f: OEM Parts					
n: Non-OEM Parts					
u: Used parts					
Savings					
Subtotal					11,635.00
Total					11,635.00

Extras

Code	Description	Price SGD
1000	CHK/ERASE FAULT CODE AFTER REPAIR	120.00*
1001	R/F TYRE	140.00*
Total Extras		260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Final Calculation

	SGD	SGD
Parts		
Total Parts	11,635.00	11,635.00
Labour Time Base 10 WU/h		
Total 145.0 WU X 48.00 SGD/h	696.00	
Total of Labour		696.00
Total Of Extras		260.00
Paint Work Time Base 10 WU/h		
Labour Cost 132.0 WU X 48.00 SGD/h	633.60	
Material Cost	306.65	
Total Paint Including Material		940.25
Repair Cost Excludes GST		13,531.25
GST (+7.0%)		947.19
Repair Cost Included GST		14,478.44

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/12/2021 17:17 (SGT)
Date of Accident	06/12/2021 20:00 (SGT)
Exact Location of Accident	Jln Anak Bukit, Singapore
Additional Location Information	turning out from car park of Bukit Timah Plaza
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV2734U
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Tay Geok Eng Carol
NRIC No	SXXXX421C
Email Address	carol.tayge@gmail.com
Mobile Phone No	(Phone) +65-96379930
Alternative Phone No	+65-96379930

VEHICLE PARTICULARS

Manufacturer	Volvo
Model	V40
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1498

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800003488-02
Cover Note Number	-

DRIVER

Name of Driver	Ong Yew Chung
NRIC No	SXXXX246H

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 421C

Vehicle Details

Vehicle No.: SLV2734U
Vehicle to be Exported: Yes
Intended Deregistration Date: 07 Dec 2021
Vehicle Make: VOLVO
Vehicle Model: V40 T2 (A)
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: B4154T52319718
Chassis No.: YV1MV28L0J2481184
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$23,530.00
Original Registration Date: 27 Dec 2017
First Registration Date: 27 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$19,942.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Dec 2027
PARF Rebate Amount: \$14,956.00

Intended COE Rebate Details

COE Expiry Date: 26 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,791.00
COE Rebate Amount: \$28,313.00
Total Rebate Amount: \$43,269.00

The information contained herein is correct as at 07 Dec 2021

OK

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/ can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature (Date & Time)

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Jenny Lim

Sketch Plan

