

Surveyor

REF: CS4/LTI 21012739/Pqy3

ASSIGNMENT

From: Sherwin Date: 17/12/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. SNM 210120721210011TAYHP


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 26K(est)

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJW6077A Yr Regn: APR 1 2010

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI Lancer 1.5EX C.C. 1,499

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No: 4A910126216

C/No: 3MYSRCY2AA 1000424

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ARUNO

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 11/12/2021 D.O.I. 17/12/2021

Survey held at Cheng Hoe Motor Rte Ltd.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front Engine bay totally burnt (Total LORS)

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - \$26,000

PAPE - \$9,687

NL - \$16,313

21/12/21@1.50pm revert to Irene Tay via Merimen.

04/01/22 Submit Extensive Total Loss Report.

Investigation: \$500/-

SCDF \$170/-

Date/Time, File Pass to?

☐

: Preli. Report

1) 04/01 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS \$ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format: MER-OD/TL-E

Lump Sum / I.B.I. (\$))